

ASSIGNMENT

From: _____ Date: _____
 Estin: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To In Vehicle No: _____
 at W/O _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBF4531C Yr Regn: 2016, Oct.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace C.D. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 286452 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KDH2010190610

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 27/08/24

Survey held at Twin Car

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP ECUS</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV:</u>
	<u>PV:</u>
	<u>Nett:</u>
	<u>081B.</u>

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: _____

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

Report Format:

Report Form / R / P / C

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MAXLINES DISTRIBUTORS
92 COMMONWEALTH DRIVE #01-716
COMMONWEALTH 16
SINGAPORE 140092

Contact : 96391418

TAX INVOICE

Repair Code : CLM16406
Date in : 26/08/2024
Vehicle Num. : GBF4531C
Model : TOYOTA HIACE 3.0 M
Chassis/Eng# : KDH2010190610/1KD2592929

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
AIRCON BLOWER ASSY <i>cracked</i>	1	1053.40	1,053.40 ✓
AIRCON COOLING COIL ASSY <i>new</i>	1	3837.80	3,837.80 +
FRONT BONNET <i>Dented</i>	1	1082.50	1,082.50 ✓
FRONT BONNET 'LOGO' EMBLEM <i>new</i>	1	59.60	59.60 ✓
FRONT BONNET HINGES L/R <i>new</i>	2	62.30	124.60 +
FRONT BONNET INNER RUBBER STOPPER L/R <i>new</i>	2	18.40	36.80 +
FRONT BONNET MECHANISM LOCK <i>new</i>	1	99.80	99.80 +
FRONT BUMPER <i>Distorted</i>	1	573.60	573.60 ✓
FRONT BUMPER FOGLAMP GARNISH L/R <i>new</i>	2	106.00	212.00 +
FRONT BUMPER INNER REINFORCEMENT VERTICAL BRACKET LH <i>new</i>	1	157.00	157.00 +
FRONT BUMPER LOWER GRILLE <i>new</i>	1	188.70	188.70 +
FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	379.40	379.40 ✓
FRONT BUMPER REINFORCEMENT BRACKET LH <i>new</i>	1	120.70	120.70 +
FRONT BUMPER SIDE RETAINER L/R <i>LH smashed</i>	2	151.80	303.60 ✓
FRONT BUMPER TOW HOOK COVER L/R <i>new</i>	2	30.10	60.20 +
FRONT DASH PANEL <i>Reis</i>	1	909.20	909.20 +
FRONT DASH PANEL INSULATOR <i>new</i>	1	281.00	281.00 +
FRONT DASHBOARD <i>new</i>	1	1028.50	1,028.50 +

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

MAXLINES DISTRIBUTORS
 92 COMMONWEALTH DRIVE #01-716
 COMMONWEALTH 16
 SINGAPORE 140092

Contact : 96391418

TAX INVOICE

Repair Code : CLM16406

Date in : 26/08/2024

Vehicle Num. : GBF4531C

Model : TOYOTA HIACE 3.0 M

Chassis/Eng# : KDH2010190610/1KD2592929

FRONT DASHBOARD REINFORCEMENT	asc in	1	805.40	805.40	+
FRONT FLOOR PANEL	Repair	1	1270.60	1,270.60	+
FRONT FLOOR PANEL WIRE HARNESS	asc in	1	526.70	526.70	+
FRONT FLOOR PANEL WIRE HARNESS COVER	changed	1	174.50	174.50	✓
FRONT FUSE BOX	asc in	1	651.70	651.70	+
FRONT GRILLE BASE	} Missing	1	602.60	602.60	✓
FRONT GRILLE LOWER OUTER COVER		1	406.70	406.70	✓
FRONT GRILLE TOP OUTER COVER		1	235.00	235.00	✓
FRONT HEADLAMP L/R	changed	2	3979.50	7959.00	✓
FRONT LH CORNER PANEL	Dented	1	284.60	284.60	✓
FRONT LH CORNER PANEL BRACKET	asc in	1	60.10	60.10	+
FRONT LH DOOR	Dented	1	2245.20	2,245.20	✓
FRONT LH DOOR CHECKER	3 for	1	96.50	96.50	+
FRONT LH DOOR HINGE (LOWER)	for	1	199.40	199.40	+
FRONT LH DOOR INNER ARCH SEAL	asc in	1	67.10	67.10	+
FRONT LH DOOR PILLAR (CENTER)	Repair	1	573.70	573.70	+
FRONT LH DOOR PILLAR (OUTER)	Dented	1	587.20	587.20	✓
FRONT LH DOOR WIRE HARNESS	asc in	1	526.70	526.70	+

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

MAXLINES DISTRIBUTORS
 92 COMMONWEALTH DRIVE #01-716
 COMMONWEALTH 16
 SINGAPORE 140092

Contact : 96391418

TAX INVOICE

Repair Code : CLM16406

Date in : 26/08/2024

Vehicle Num. : GBF4531C

Model : TOYOTA HIACE 3.0 M

Chassis/Eng# : KDH2010190610/1KD2592929

FRONT LH DOOR WIRE HARNESS COVER <i>could</i>	1	948.10	948.10 <i>218</i>
FRONT LH STEP GARNISH <i>could</i>	1	175.40	175.40 ✓
FRONT LH STEP PANEL <i>Buckled</i>	1	78.90	78.90 ✓
FRONT SUPPORT PANEL (TOP PANEL) <i>near</i>	1	433.90	433.90 ✓
Subtotal before discount			23,041.20
Percentage discount 25%			5,760.30
Sub-total 1			17,280.90
FRONT BUMPER CLIPS - SET <i>3</i>	1	80.00	80.00 <i>30</i>
FRONT GRILLE CLIPS - SET <i>3</i>	1	40.00	40.00 <i>30</i>
FRONT LH DOOR COMPANY STICKER <i>nu</i>	1	25.00	25.00 ✓
FRONT LH STEP GARNISH CLIPS - SET <i>nu</i>	1	30.00	30.00 <i>10</i>
Subtotal before discount			175.00
Percentage discount 0%			0.00
Sub-total 2			175.00
Parts-total			17,455.90

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To remove, change dashboard fascia and transfer where necessary.

80.00 *30*
 80.00 *60*
 450.00 *250*

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MAXLINES DISTRIBUTORS
92 COMMONWEALTH DRIVE #01-716
COMMONWEALTH 16
SINGAPORE 140092

Contact : 96391418

TAX INVOICE

Repair Code : CLM16406

Date in : 26/08/2024

Vehicle Num. : GBF4531C

Model : TOYOTA HIACE 3.0 M

Chassis/Eng# : KDH2010190610/1KD2592929

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

2,600.00 1000

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

2,800.00 10400

To apply anti-rust chemical on repaired and replaced panel.

140.00 100

Labour Total

6,150.00

Parts & Labour Total

23,605.90

*** This is a computer-generated document which requires no signature.***

page 4

Adrian C
H/S 29/08/24
09 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: