

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III24080463/AQP3E2
Date: 14/11/2024REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0005826_03
Claimant Vehicle No :	SLG266X	Insured Vehicle No :	SNB9042T
Date of Loss:	23/08/2024	Nature of Claim:	TP
		Claim No:	MFL2024D0010002

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG266X	Engine No:	LEB5910075
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31210064
Reg. Date:	19/09/2016 (Man. Year: 2016)	Odometer:	297188 km
Colour:	Bronze		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,327.36	734.00	8,593.36	92.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,090.00	500.00	3,590.00	87.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,417.36	1,234.00	12,183.36	90.80
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	13,417.36	1,000.00	12,417.36	92.55
+ GST 9.00/9.00% (S\$)	1,207.56	90.00	1,117.56	92.55
Nett Amount (S\$)	14,624.92	1,090.00	13,534.92	92.55

INSPECTION

Date of Assignment:	27/08/2024	
Date Inspected:	27/08/2024	Inspected At: A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #04-20 Premier Singapore 415875
Estimated Period of Repair:	2.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2024)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG266X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	236.80 FL	*- FL
2	1		*REAR TAILGATE	Not Necessary	1,450.30 FL	*- FL
3	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	487.80 FL	*- FL
4	1		*REAR TAILGATE LOCK	Not Necessary	360.80 FL	*- FL
5	1		*REAR TAILGATE LOGO	Not Necessary	57.10 FL	*- FL
6	1		*REAR TAILGATE RUBBER	Not Necessary	72.20 FL	*- FL
7	1		*REAR TAILGATE N/S SIDE REFLECTOR	Not Necessary	401.20 FL	*- FL
8	1		*REAR TAILGATE VEZEL EMBLEM	Not Necessary	61.10 FL	*- FL
9	1		*REAR TAILLAMP - LH	Not Necessary	698.70 FL	*- FL
10	1		*REAR END PANEL	Not Necessary	625.70 FL	*- FL
11	1		*REAR END PANEL INNER GARNISH	Not Necessary	101.70 FL	*- FL
12	1		*REAR BUMPER	Deformed	1,190.40 FL	*880.00 FL
13	1		*REAR BUMPER LOWER DIFFUSER	Not Necessary	241.40 FL	*- FL
14	1		*REAR BUMPER LOWER LID	Not Necessary	825.40 FL	*- FL
15	1		*REAR BUMPER REFLECTOR	Not Necessary	60.10 FL	*- FL
16	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	71.60 FL	*- FL
17	2		*REAR BUMPER PDC SENSORS	Not Necessary	621.00 FL	*- FL
18	2		*REAR BUMPER REVERSE SENSOR HOLDERS	Not Necessary	60.00 FL	*- FL
19	1		*REAR FENDER - LH	Not Necessary	761.80 FL	*- FL
20	1		*REAR FENDER INNER TRIM BOARD	Not Necessary	546.20 FL	*- FL
21	1		*REAR FENDER WHEEL ARCH GARNISH - LH	Not Necessary	182.40 FL	*- FL
22	1		*REAR WHEEL RIM - LH	Not Necessary	950.00 FL	*- FL
23	1		*FRONT DOOR SIDE MIRROR ASSY - RH	Not Necessary	745.50 FL	*- FL
24	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
25	1		*SET REAR TAILGATE INNER TRIM BOARD CLIP	Not Necessary	50.00 FS	*- FS
26	1		*REAR TYRE	Not Necessary	500.00 FS	*- FS
27	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,489.20	910.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,161.84	176.00
Total Parts (\$\$)	9,327.36	734.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	80.00	0.00
2	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR	New	180.00	0.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR	New	80.00	0.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	0.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
7	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	200.00	0.00
8	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,600.00	200.00
9	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,500.00	250.00
Gross Labour Cost (\$)			4,090.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >