A-Tec Automotive Pte Ltd 8 Kaki Bukit Ave 4 #04-20 Premier Singapore 415875

TPILI

Xiao Chen.

D.O.A: 23 Aug 2024

OWNER: STARK HOLDINGS INN BIKE LEASING PTE LTD

SLG266X Honda Vezel

No	Otv	Parts Description	stimated arts Price
1	1	Rear windscreen moulding	\$ 236.80
2	1	Rear tailgate	\$ 1,450.30
3	1	Rear tailgate inner trim board	\$ 487.80 >
4	1	Rear tailgate lock	\$ 360.80
5	1	Rear tailgate logo	\$ 57.10
6	1		\$ 72.20
7	1	Rear tailgate rubber Rear tailgate n/s side reflector	\$ 401.20 ×
8	1	Rear tailgate "VEZEL" emblem	\$ 61.10
9	1	Rear taillamp -LH	\$ 698.70
10	1	Rear end panel	\$ 625.70
11	1	Rear end panel inner garpish	\$ 101.70
12	1	Rear bumper Dehned	\$ 1,190.40
13	1	Rear bumper lower diffuser	\$ 241.40
14	1	Rear bumper lower lid	\$ 825.40
15	1	Rear bumper reflector	\$ 60.10
16	2	Rear bumper side retainers	\$ 71.60
17	2	Rear humner PDC sensors	\$ 621.00
18	2	Rear bumper reverse sensor holders Rear fender -LH	\$ 60.00 4
19	1	Rear fender -LH	\$ 761.80 +
20	1	Rear fender inner trim board	\$ 546.20
21	1	Rear fender wheel arch garnish -LH	\$ 182.40
22	1	Rear wheel rim -LH	\$ 950.00 +
23	1	Front door side mirror assy -RH	\$ 745.50
43	1	Tiont door side innier desy	\$ 10,809.20
		less 20%	\$ 2,161.84
			\$ 8,647.36

No Q	ty Parts Description			stimated rts Price
1 2 3 4	Special Nett Items Rear windscreen sealant Rear tailgate inner trim board clip (1 set) Rear bumper clip (1 set) Rear tyre He w	ne 30	\$ \$ \$	80.00 ± 50.00 ± 50.00 ± 680.00
	Total n	arts .	•	9.327.36

			Labour Charges
No	Description	\$	80.00
1	To remove, refit, replaced damaged lamps and check	Φ	30.00
	up rear electrical wiring	•	180.00
2	To remove and refit inner garnishes, inner trim to	\$	180.00
	assist repair.	•	120.00- 50
3	To remove and refit rear reverse sensor.	\$	120.00 50
4	To transfer rear tailgate mechanism and wiring	\$	80.00 ×
	assembly to assist repair.		
5	To conduct wheel alignment.	\$	150.00 ×
6	To remove and refit rear windscreen glass.	\$	180.00 ×
7	To apply undercoating on repaired and replaced panel.	\$	200.00
8	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the	\$	1,600.00 200
9	accident. To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$	1,500.00 250
	Total labour:	\$	4,090.00
	Total parts : Total labour : Total repair cost :	\$ \$ \$	9,327.36 4,090.00 13,417.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

3-phature

Adran Cg Hs 27/08/24. 02/08/24. Dell 1234 L/S: IK.