

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2401463

INV Date : 20-11-2024

Reference CD/FCI24080465/Rua3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMV 8238J
Insured Veh. SHA 5757S
Claim No. D24007559MFCT/CTPL/TPD 2
Policy No. D-24101861MFCT
Accident Date 26/08/2024
Inspection Date 03/09/2024

Description	Amount
Third Party Express Settlement	350.00
Sub-Total	350.00
GST (9%)	31.50
Grand Total	381.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CD/FCI24080465/Rua3q2
16 RAFFLES QUAY	Date:	20/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SHA 5757S	Veh. Inspected	SMV 8238J
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24007559MFCT/CTPL/TPD 2	Excess	\$0.00
Assign From	JASON TEA	Assign Date	27/08/2024

2. Vehicle Details

Make & Model	HYUNDAI CN7 AVANTE 1.6 DOHC CVT S	C.C	1598
Engine No.	G4FMLU555226	Year of Reg.	26/10/2020
Chassis No.	KMHLN41ETMU066548	Colour	WHITE
Odometer	54875 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55 R16	MICHELIN	6
L/H Front Tyre	205/55 R16	MICHELIN	6
R/H Rear Tyre	205/55 R16	MICHELIN	6
L/H Rear Tyre	205/55 R16	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/08/2024	Inspection Date	03/09/2024
Survey held at	KOMOCO MOTORS PTE LTD 253 ALEXANDRA ROAD #01-01 SINGAPORE 159936.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMV 8238J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
10	RR BUMPER CLIP	NOT NECESSARY	\$20.00	\$0.00
1	PANEL ASSY FRONT DOOR LH	BENT	\$2,471.00	\$2,471.00
1	GARNISH ASSY -DR FRAME LH	NECESSARY	\$40.00	\$40.00
1	MOULDING ASSY -FRT DR FRAME ,LH	NECESSARY	\$56.00	\$56.00
1	MIRROR ASSY -OUTSIDE RR VIEW LH	CUT	\$852.00	\$852.00
	LESS 20.00% DISCOUNT		(\$687.80)	(\$683.80)
			\$2,751.20	\$2,735.20

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$40.00	\$20.00
			\$40.00	\$20.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CARRY OUT ACCIDENT BODY REPAIR -FRT LH DOOR.	NOT NECESSARY	\$840.00	\$420.00
	COMPLETE PUTTY AND SPRAY PAINT ALL AFFECTED AREAS -FRT LH DOOR /FRT LH WING MIRROR		\$960.00	\$440.00
	TO SUPPLY DOOR SEALANT		\$100.00	\$100.00
	TO TRANSFER DOOR MECHANISM		\$210.00	\$210.00
	TO REPAIR FRT LH DOOR PANEL		\$420.00	\$0.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AFTER ACCIDENT REPAIR		\$180.00	\$180.00
	TO PERFORM PREPROGRAMME & AFTER ACCIDENT REPAIR		\$180.00	\$180.00
			\$2,890.00	\$1,530.00

GRAND TOTAL			\$5,681.20	\$4,285.20
	RECOMMENDED COST OF REPAIRS			\$4,285.20

Report Ref No: CD/FCI24080465/Rua3q2

MRB

MOHAMMED RASUL BIN MOHD YUNUS



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SMV 8238J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 2 of 7)

PHOTOGRAPHS FOR VEHICLE NO. : SMV 8238J






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 7)

PHOTOGRAPHS FOR VEHICLE NO. : SMV 8238J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 7)


PHOTOGRAPHS FOR VEHICLE NO. : SMV 8238J





PHOTOGRAPHS FOR VEHICLE NO. : SMV 8238J



PHOTOGRAPHS FOR VEHICLE NO. : SMV 8238J



PHOTOGRAPHS FOR VEHICLE NO. : SMV 8238J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SMV 8238J

