Ø1001

源摩哆廠 GUAN MOTOR WORKS

Dunaness Regit No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tal: 6453-6111 Fax: 6453-8292 Ft/P: 9742-6003

REPAIR ESTIMATE SLQ1574Y

| No. | Qty | | | | |
|-----|--|---------|-------|----------|------|
| 1 | <u>List Items</u> 1 RH lower rocker panel outer cover/skirting | g | Bug/1 | 580.00 | |
| | | | Š | 580.00 | |
| | | Less 5% | \$ | 29.00 | |
| | | Total: | \$ | 551.00 | |
| 1 | <u>Labour</u> Labour Charges for remove, refit, panel beat an | d | \$ | 400.00 | 254 |
| 2 | replacement of damages. To putty and spray Spray Paintings charges. | | \$ | 700.00 | 6001 |
| 3 | To check wirings. | | \$ | 40.00 | 201 |
| 4 | To supply and apply anti rust treatment. | | \$ | M 30.00 | _ × |
| | | Total: | \$ | 1,170.00 | _ |
| | | | | | |

Total Parts and Labour : \$ 1,721.00

Nor Norhand 11 ly B Mehmy Atle Pains 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: