

ASS. REC. BY:

REF:

F02/

CS/F024060130/Knh3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNJ9802A

Yr Regn:

07, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M S400

C.C.

2996

Colour

M-Black

A/C:

Insured / Std / NI / NA

Sp. Reading

116490

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2221652A 275218

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: GY

245/40R20

R: Nic

275/35R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

6

mm

L/Bal.

5

mm

L/Bal.

6

mm

D.O.A.

13/6/24

D.O.I.

19/6/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/6 11:20 8895d Catch (Red, #6325.10, 419)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Date: 18/06/2024

Vehicle No: SNJ9802A

Model: MERCEDES BENZ S400L

Chassis: WDD2221652A275218-2016

Reg.Year: 2016

*NOT Withair
11 Lm @ 8950/-*

Running After Pains

Third Party Insurer: MS FIRST CAP

Third Party Veh No: SHC1992U

Date of Accident: 13/06/2024

Estimator: TING AN

Surveyor:

4 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1	<i>Bu</i>	\$2,495.00 ✓
2	REAR BUMPER SIDE RETAINER RH	1	<i>cm</i>	\$81.00 ✓
3	REAR BUMPER PARKING SENSOR	1	<i>in</i>	\$243.00 ✓
4	REAR BUMPER CHROME MOULDING RH	1	<i>me</i>	\$162.00 ✓
5	REAR TAIL LAMP RH	1	<i>in</i>	\$1,215.00 X
6	REAR ABSORBER RH <i>4520</i>	1		\$5,243.00 ✓
7	REAR LOWER ARM RH <i>326</i>	1	<i>By</i>	\$667.00 ✓
8	REAR KNUCKLE ARM RH <i>1938</i>	1	<i>By</i>	\$2,599.00 ✓
9	REAR WHEEL BEARING RH	1	<i>me</i>	\$353.00 ✓
10	REAR STABILISER LINKAGE RH	1	<i>in</i>	\$181.00 X
11	REAR FENDER RH	1		REPAIR
SUB TOTAL				\$13,239.00
LESS 10%				-\$1,323.90
PARTS TOTAL				\$11,915.10

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>me</i> \$50.00 ✓
2	REAR RIM RH <i>117 950</i>	1		<i>no</i> \$1,000.00 ✓
S/N TOTAL				\$1,050.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

400
\$700.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR FENDER RH & ETC.

440
\$600.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER PARKING SENSOR & ETC.

\$120.00 *60*

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

no \$150.00 X

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18/06/2024
Vehicle No: SNJ9802A
Model: MERCEDES BENZ S400L
Chassis: WDD2221652A275218-2016
Reg.Year: 2016

Third Party Insurer: MS FIRST CAP
Third Party Veh No: SHC1992U
Date of Accident: 13/06/2024
Estimator: TING AN
Surveyor:

LABOUR CHARGES TO REMOVE & REPLACE REAR ABSORBER RH, REAR LOWER ARM RH,
REAR KNUCKLE ARM RH, REAR WHEEL BEARING RH & ETC.

\$400.00 *200/*

TO WHEEL ALIGNMENT & BALANCING.

\$100.00 *20/*

TO TUFF KOTE & UNDERSEAL MATERIALS.

na \$120.00 *X*

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00 *20/*

LABOUR TOTAL \$2,310.00

TING AN

TOTAL \$15,275.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

