

ASS. REC. BY:

REF:

A161

C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Hui Yau

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 1.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNR 5461J Yr Regn: 06, 24

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A) WagonMake: Toy Noah C.C. 1797Colour: h. Black A/C: Insured / Std / NI / NASp. Reading: 60d1 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZWR 90 0180156Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: MH7S/Rlm / STD A/Rlm orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 24/8/24 D.O.I. 27/8/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Owner insist to change tailgate29/8 8 3906-44 Cabin

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation: _____
S - RS. _____ \$

Fees _____

Others _____

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I.: (\$ _____)

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

24/08/2024

Owner: PRAMKUMAR

3906.44

Not Authorized
Survey B4 pay
3 days

ESTIMATE TO REPAIR TOYOTA NOAH 1.8X - SNR5461J

1pc	rear tailgate		<i>nd/way</i>	\$	1,350.25	✓
1pc	rear tailgate windscreen glass moulding	<i>184.40</i>	<i>nd</i>	\$	281.50	✓
1pc	rear tailgate "TOYOTA" logo		<i>nd</i>	\$	85.20	X
1pc	rear tailgate "NOAH" emblem		<i>nd</i>	\$	75.20	X
1pc	rear tailgate "HYBRID" emblem		<i>nd</i>	\$	78.50	✓
1pc	rear tailgate outer garnish		<i>nd</i>	\$	481.50	X
1pc	rear tailgate inner lock		<i>nd</i>	\$	481.20	X
1pc	rear tailgate inner garnish		<i>nd</i>	\$	525.20	X
1pc	rear tailgate inner rubber		<i>nd</i>	\$	181.50	X
1pc	rear bumper		<i>nd</i>	\$	1,250.20	✓
2pcs	rear bumper reflector @\$121.50		<i>nd</i>	\$	243.00	X
2pcs	rear bumper centre parking sensor @\$380.50	<i>286.90</i>	<i>nd</i>	\$	761.00	✓
1pc	rear end panel		<i>nd</i>	\$	781.20	X
1pc	rear end panel inner garnish	<i>298.10</i>	<i>nd</i>	\$	381.50	X
					\$	6,956.95
less 25%					\$	1,739.24
					\$	5,217.71

1set rear number plate & casing s.nett \$ 50.00 X

remove & refix rear winscreen glass	\$	120.00	✓
sealant	\$	80.00	<i>40.50</i>
wirring	\$	80.00	<i>15L</i>
tuffkote	\$	80.00	<i>30L</i>
spray painting	<i>400L</i> \$	1,000.00	<i>400L</i>
labour charges	\$	1,000.00	<i>500L</i>
Total	\$	7,627.71	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: