



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 5816E

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | RIM | TO REPAIR SEE LABOUR | 345.00 | - |
| 1 | HEADLIGHT | BROKEN | 450.00 | 305.00 |
| 1 | HEADLIGHT BRACKET | BENT | 95.00 | 95.00 |
| 1 | TOP FEARING | CRACKED | 250.00 | 185.00 |
| 1 | LEVER | SCRATCHED | 30.00 | 30.00 |
| 1 | FRONT MUDGUARD | CRACKED | 75.00 | 65.00 |
| 1 | HANDLE BAR | BENT | 180.00 | 126.00 |
| 1 | DISC | SCRATCHED | 125.00 | 85.00 |
| 1 | FORK | BENT | 350.00 | 350.00 |
| 1 | SPEEDOMETER | CRACKED | 350.00 | 350.00 |
| 1 | UNDER BRACKET | BENT | 280.00 | 245.00 |
| 1 | SIGNAL LIGHT | SCRATCHED | 30.00 | 30.00 |
| 1 | THROTTLE CABLE | SERVICEABLE | 80.00 | - |
| 1 | CLUTCH CABLE | CUT | 30.00 | 30.00 |
| 2 | AIR INTAKE L&R | SERVICEABLE | 90.00 | - |
| 2 | SIDE COWLING L&R | CRACKED | 360.00 | 230.00 |
| 1 | FOOTREST | SERVICEABLE | 90.00 | - |
| 1 | STEERIG CONE | NECESSARY | 120.00 | 55.00 |
| 1 | RIM SHAFT | SERVICEABLE | 45.00 | - |
| 1 | WIND SCREEN | CRACKED | 150.00 | 45.00 |
| 1 | MIRROR | SCRATCHED | 80.00 | 72.00 |
| 1 | EXHAUST PIPE MUFFLER | SERVICEABLE | 650.00 | - |
| 1 | SIGNAL SWICTH | CUT | 95.00 | 75.00 |
| | LESS 10% DISCOUNT | | -435.00 | -237.30 |
| | | | 3,915.00 | 2,135.70 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | NO. PLATE (SN) | MISSING | 25.00 | 10.00 |
| | | | 25.00 | 10.00 |

Report Ref No. CS/UOI24080474/Rqp3e2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|-----------|---------------------------|-------------------|
| | <u>LABOUR</u> | | | |
| | TOWING FEE. | | 60.00 | 60.00 |
| | ALIGN BODY. | | 200.00 | 150.00 |
| | LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF RIM. | | 400.00 | 300.00 |
| | PAINTING. | | 400.00 | 400.00 |
| | | | 1,060.00 | 910.00 |
| | GRAND TOTAL | | 5,000.00 | 3,055.70 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 2,450.00 |

Report Ref No. CS/UOI24080474/Rqp3e2(N)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.