

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24060132/KMA3Q2**Date:** 11/10/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210134799  
**Claimant Vehicle No :** SMW2177K **Insured Vehicle No :** SLP1054L  
Date of Loss: 15/05/2024 Nature of Claim: TP Claim No: 6865877214SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMW2177K**  
Make & Model: TOYOTA LEXUS, 2.5 ES250 4DR SEDAN (AUTO) EXECUTIVE (A) Engine No: A25A5459720  
Reg. Date: 10/11/2020 (Man. Year: 2020) Chassis No: JTHB11B1202030718  
Colour: Metallic Grey Odometer: 162797 km  
Engine Capacity: 2487 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 235/45 R18 Rear Tyre Size: 235/45 R18  
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm  
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                            | 5,293.25          | 1,963.65          | 3,329.60          | 62.90         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour                                           | 2,560.00          | 1,175.00          | 1,385.00          | 54.10         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing                                           | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>              | <b>7,853.25</b>   | <b>3,138.65</b>   | <b>4,714.60</b>   | <b>60.03</b>  |
| <b>Approved Total (Overridden) (S\$)</b>         |                   | <b>2,500.00</b>   |                   |               |
| <b>(S\$)</b>                                     | 7,853.25          | 2,500.00          | 5,353.25          | 68.17         |
| <b>+ GST 9.00/9.00% (S\$)</b>                    | 706.79            | 225.00            | 481.79            | 68.17         |
| <b>Nett Amount (S\$)</b>                         | <b>8,560.04</b>   | <b>2,725.00</b>   | <b>5,835.04</b>   | <b>68.17</b>  |
| <b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b> |                   | 400.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                    |                   | 27.25             |                   |               |
| <b>Nett Liability (S\$)</b>                      |                   | <b>3,152.25</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>               |                   | <b>3,150.00</b>   |                   |               |

**INSPECTION**

Date of Assignment: 18/06/2024  
Date Inspected: 18/06/2024 Inspected At: Hui Yang Motor Pte Ltd (HQ)  
176 Sin Ming Drive #04-02, Sin Ming AutoCare  
Singapore 575721  
Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                            | Condition   | Repairer's  | Amount       |
|-----|-----|----------|----------------------------------------|-------------|-------------|--------------|
| 1   | 1   |          | *REAR BOOT COVER                       | Repair      | 1,850.50 FL | *- FL        |
| 2   | 1   |          | *REAR BOOT COVER LEXUS EMBLEM          | Necessary   | 121.50 FL   | *98.90 FL    |
| 3   | 1   |          | *REAR BOOT COVER ES250 EMBLEM          | Necessary   | 118.20 FL   | *96.20 FL    |
| 4   | 1   |          | *REAR BUMPER                           | Buckled     | 1,350.50 FL | *1,280.00 FL |
| 5   | 2   |          | *REAR BUMPER SIDE RETAINER             | Serviceable | 264.50 FL   | *- FL        |
| 6   | 1   |          | *REAR BUMPER LOWER GARNISH             | Mtg Cracked | 381.50 FL   | *381.50 FL   |
| 7   | 1   |          | *REAR BUMPER LOWER GARNISH CHROME      | Necessary   | 181.20 FL   | *181.20 FL   |
| 8   | 2   |          | *REAR BUMPER LOWER GARNISH SIDE CHROME | Serviceable | 317.00 FL   | *- FL        |
| 9   | 2   |          | *REAR BUMPER CENTRE PARKING SENSOR     | Serviceable | 563.00 FL   | *- FL        |
| 10  | 1   |          | *REAR BUMPER REINFORCEMENT             | Buckled     | 385.20 FL   | *385.20 FL   |
| 11  | 1   |          | *REAR BUMPER SPONGE                    | Cracked     | 195.20 FL   | *195.20 FL   |
| 12  | 1   |          | *REAR END PANEL                        | Repair      | 781.50 FL   | *- FL        |
| 13  | 1   |          | *REAR END PANEL INNER GARNISH          | Serviceable | 481.20 FL   | *- FL        |
| 14  | 1   |          | *SET REAR NUMBER PLATE & CASING        | Serviceable | 50.00 FS    | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>7,041.00</b> | <b>2,618.20</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 1,747.75        | 654.55          |
| <b>Total Parts (\$\$)</b>                                  | <b>5,293.25</b> | <b>1,963.65</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars    | Lab.Type | Repairer's      | Amount          |
|---------------------------------|----------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                |          |                 |                 |
| 1                               | WIRING         | New      | 80.00           | 15.00           |
| 2                               | TUFFKOTE       | New      | 80.00           | 0.00            |
| 3                               | SPRAY PAINTING | New      | 1,200.00        | 660.00          |
| 4                               | LABOUR CHARGES | New      | 1,200.00        | 500.00          |
| <b>Gross Labour Cost (\$\$)</b> |                |          | <b>2,560.00</b> | <b>1,175.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >