

ASS. REC. BY:

REF:

AIG / 24060132 / 1/CPA3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

BMW 2177K Yr Regn: 11, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Lexus ES250 c.c. 2487

Colour

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

162794

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTHB11B1202030718

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F:

R:

235/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

15/5/24

D.O.I.

18/6/2024

Survey held at

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/6 11:00 82500h Car

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

AIC.
Kunroth
18/06/24

15/05/2024

Owner: ANG CHIN KENG

Not withair
C/Ly @ 2500/
Resurvey After Rainy
04days

ESTIMATE TO REPAIR TOYOTA LEXUS ES250 - SMW2177K

1pc	rear boot cover	
1pc	rear boot cover "LEXUS" emblem	98.90
1pc	rear boot cover "ES250" emblem	96.20
1pc	rear bumper	1280
2pcs	rear bumper side retainer @\$132.25	
1pc	rear bumper lower garnish	
1pc	rear bumper lower garnish chrome	
2pcs	rear bumper lower garnish side chrome @\$158.50	
2pcs	rear bumper centre parking sensor @\$281.50	
1pc	rear bumper reinforcement	
1pc	rear bumper sponge	
1pc	rear end panel	
1pc	rear end panel inner garnish	

R	\$ 1,850.50	X
Ma	\$ 121.50	—
Ma	\$ 118.20	—
Bu	\$ 1,350.50	—
SL	\$ 264.50	X
MSL	\$ 381.50	2
Ma	\$ 181.20	2
SL	\$ 317.00	X
SL	\$ 563.00	X
Bu	\$ 385.20	2
CM	\$ 195.20	2
R	\$ 781.50	X
SL	\$ 481.20	X

less 25%

\$ 6,991.00
\$ 1,747.75
\$ 5,243.25

1set rear number plate & casing

s.nett \$ 50.00 X

wiring
tuffkote
spray painting
labour charges
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

\$ 80.00 15/
\$ 80.00 X
\$ 1,200.00 660/
\$ 1,200.00 500/
\$ 7,853.25

