

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI24080486/EQP3E2  
**Date:** 05/09/2024REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS008700
<b>Claimant Vehicle No :</b>	SHA3095G	<b>Insured Vehicle No :</b>	GBG4111B
Date of Loss:	27/08/2024	Nature of Claim:	TP
		Claim No:	M2404914

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHA3095G</b>	Engine No:	G4LEKU401755
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVLU187875
Reg. Date:	16/01/2020 (Man. Year: 2019)	Odometer:	577856 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Davanti 5 mm	Rear Left Side:	Davanti 5 mm
Front Right Side:	Davanti 5 mm	Rear Right Side:	Davanti 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>	
Parts	4,379.60	3,603.80	775.80	17.71	
Miscellaneous Items	12.00	12.00	0.00	0.00	
Labour	1,830.00	1,510.00	320.00	17.49	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>6,221.60</b>	<b>5,125.80</b>	<b>1,095.80</b>	<b>17.61</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>4,100.00</b>			
	<b>(S\$)</b>	6,221.60	4,100.00	2,121.60	34.10
	<b>+ GST 9.00/9.00% (S\$)</b>	559.94	369.00	190.94	34.10
	<b>Nett Amount (S\$)</b>	<b>6,781.54</b>	<b>4,469.00</b>	<b>2,312.54</b>	<b>34.10</b>

INSPECTION

Date of Assignment:	28/08/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	29/08/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 05 Sep 2024)
<b>Parts:</b> 192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHA3095G)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID - HYBRID	Necessary	24.30 FL	*24.30 FL
2	1		*BOOTLID - IONIQ	Necessary	31.30 FL	*31.30 FL
3	1		*BOOTLID - H	Necessary	28.00 FL	*28.00 FL
4	1		*BOOTLID	Dented	2,549.70 FL	*2,549.70 FL
5	1		*REAR BUMPER	Broken	459.40 FL	*459.40 FL
6	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
7	2		*REAR BUMPER REINFORCEMENT BRKT RH / LH	Not Necessary	276.20 FL	*- FL
8	1		*REAR BUMPER CENTRE MOULDING	Broken	451.25 FL	*451.25 FL
9	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
10	1		*REAR BUMPER REFLECTOR LH	Not Necessary	41.45 FL	*- FL
11	1		*REAR BUMPER SIDE BRKT LH	Not Necessary	55.80 FL	*- FL
12	1		*BOOTLID - COMFORTDELGRO	Necessary	30.00 F	*30.00 F
13	1		*BOOTLID - 65521111	Necessary	30.00 F	*30.00 F
14	1		*BOOTLID - ZIG	Necessary	40.00 F	*40.00 F
15	1		*REVERSE SENSORS	Broken	180.00 F	*180.00 F
16	1		*BOOTLID ADV.STICKER	Necessary	100.00 F	*100.00 F
17	2		*REAR FENDER ADV.STICKER RH / LH	Necessary	200.00 F	*200.00 F
18	2		*REAR WINDSCREEN SEALANT	Necessary	92.00 F	*92.00 F
19	1		*REAR BUMPER TOW COVER	Cut	98.80 FL	*98.80 FL
20	1		*REAR BUMPER FOGLAMP	Not Necessary	201.50 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,306.50</b>	<b>4,336.75</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	926.90	732.95
<b>Total Parts (S\$)</b>	<b>4,379.60</b>	<b>3,603.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	12.00	12.00
			<b>Sub Total (\$)</b>	<b>12.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	760.00
2	SPRAY PAINTING	New	600.00	560.00
3	TUFF KOTE	New	60.00	20.00
4	R/I REAR WINDSCREEN GLASSES	New	250.00	150.00
5	R/I REVERSE SENSORS	New	120.00	20.00
			<b>Gross Labour Cost (\$)</b>	<b>1,830.00</b>
				<b>1,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >