11/15/24, 1:35 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24080489/ANP3M4

Date: 15/11/2024

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1002137509

Claimant Vehicle

No: Insured Vehicle No: FBN1964P

Date of Loss: 27/08/2024 Nature of Claim: TP Claim No: 371612

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ4401T

 Make & Model:
 HONDA VEZEL, 1.5 X (A)
 Engine No:
 L15B4405275

 Reg. Date:
 11/07/2017 (Man. Year: 2016)
 Chassis No:
 RU11205272

 Colour:
 Silver
 Odometer:
 121278 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,954.35	1,639.82	2,314.53	58.53
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,050.00	550.00	1,500.00	73.17
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,004.35	2,189.82	3,814.53	63.53
	Approved Total (Overridden) (S\$)		1,550.00		
	Nett Amount (S\$)	6,004.35	1,550.00	4,454.35	74.19

INSPECTION

Date Inspected:

Date of Assignment: 29/08/2024

HUA MENG SPRAY PAINTING WORKSHOP

1 KAKI BUKIT AVENUE 6

#01-61 AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: HUEY YON

29/08/2024 Inspected At:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Nov 2024)

Parts: M1-SUV HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLQ4401T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty F	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	636.18 FL	*636.18 FL
2	1		*REAR BUMPER LH REFLECTOR	Cut	196.42 FL	*196.42 FL
3	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	380.00 FL	*- FL
4	1		*REAR BUMPER LH SIDE HOLDER	Not Necessary	20.93 FL	*- FL
5	1		*REAR LH LAMP	Cut	576.03 FL	*475.00 FL
6	1		*REAR LH LAMP LOWER GARNISH	Deformed	186.41 FL	*186.41 FL
7	1		*REAR LH FENDER SIDE GARNISH	Not Necessary	176.18 FL	*- FL
8	1		*REAR TAILGATE	Repair	1,266.03 FL	*- FL
9	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	55.77 FL	*55.77 FL
10	1		*REAR TAILGATE H LOGO	Not Necessary	27.48 FL	*- FL
11	1		*REAR LH SPORT RIM	Cut	984.51 FN	*400.00 F
12	1		*REAR LH TYRE	Not Necessary	437.00 FL	*- FL
F=Fra	anchise pa	art. L=ListIte	mDisc. N=NettItemDisc.	_		
				Sub Total (S\$)	4,942.94	1,949.78

 Sub Total (S\$)
 4,942.94
 1,949.78

 as 20.00/20.00% (S\$)
 791.69
 309.96

- List Item Discount on L Items 20.00/20.00% (S\$) 791.69 309.96 - Nett Item Discount on N Items 20.00/0.00% (S\$) 196.90 0.00

Total Parts (S\$) 3,954.35 1,639.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			,
1	REMOVE, REINSTALL REVERSE SENSOR	New	150.00	50.00
2	REMOVE, REPLACE + REPAIR CONSISTENT TO THE ACCIDENT	New	900.00	200.00
3	RESPRAY PAINTING	New	1,000.00	300.00
	Gross Labour Cost (S\$)		2,050.00	550.00
	Report was unsubmitted during thi	s print-out.		

< END OF ESTIMATES >