



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : TP / 24012-07/MY / 2024
Date of Report : 25 Jul 2024

A. Inbah
C/o No. 1 Kaki Bukit Ave 6
#01-53/55 AutoBay@Kaki Bukit
Singapore 417883

**THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 17 Jul 2024**

Workshop Address : Bluwel Automotive Service Pte Ltd
No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

As per your instruction dated **22 Jul 2024** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SNC 375 L**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: SNC 375 L	Engine No	: L13B14100556
Model	: Honda Jazz	Mileage	: 59080
Year / Capacity	: 2019/1318	Colour	: Black
Chassis No	: JHMGK3850KS211410		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 205/50 R16	Yokohama	6.00	mm	Sport
REAR O/S	: 205/50 R16	Yokohama	6.00	mm	Sport
FRONT N/S	: 205/50 R16	Yokohama	6.00	mm	Sport
REAR N/S	: 205/50 R16	Yokohama	6.00	mm	Sport



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4/5 5300
841

4. Estimated normal period of repair : 11 working days to complete.

5. Enclosed number of photograph : 130 copies.

6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.

7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SNC 375 L**
 Report No: **TP/ 24012-07/MY / 2024**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Rear tailgate 797.80	Damage	\$ 1261.93	\$ 1261.93 ✓
2	Rear tailgate dampers *	Damage	\$ 303.74	\$ 303.74 ✓
1	Rear tailgate inner handle	Damage	\$ 34.40	\$ 34.40 ✓
1	Rear tailgate inner board	Intact <i>su</i>	\$ 267.07	\$ <i>9</i>
2	Rear tailgate lamps	Intact <i>su</i>	\$ 522.40	\$ <i>x</i>
1	Rear tailgate inner lock 95.60	Damage	\$ 282.89	\$ 282.89 ✓
1	Rear tailgate rubber 92.30	Damage	\$ 123.07	\$ 123.07 ✓
1	Rear tailgate 'JAZZ' emblem	Necessary	\$ 47.87	\$ 47.87 ✓
2	Rear taillamps 280 x 2 = 560	Damage	\$ 923.56	\$ 923.56 ✓
2	Rear taillamp panels	Repair <i>R</i>	\$ 340.00	\$ <i>x</i>
1	Rear end panel 349.80	Damage	\$ 592.00	\$ 592.00 ✓
1	Rear end panel inner garnish	Damage	\$ 87.20	\$ 87.20 ✓
1	Rear bumper 506.80	Damage	\$ 785.37	\$ 785.37 ✓
2	Rear bumper retainers	Damage	\$ 72.60	\$ 72.60 ✓
1	Rear number plate	Intact <i>su</i>	\$ 50.00	\$ <i>x</i>
1	Rear spare tyre panel 1140.80	Damage	\$ 1682.67	\$ 1682.67 ✓
1	Rear spare tyre tool sponge tray	Damage	\$ 294.13	\$ 294.13 ✓
1	Rear fender	Repair <i>R</i>	\$ 922.82	\$ <i>x</i>
2	Rear fender inner garnishes <i>MS replaced</i>	N/S Damage	\$ 694.14	\$ 347.07 <i>1/2</i>
			\$ 9287.86	\$ 6838.50
<u>Special Nett Items</u>				
1	Rear windscreen seal	Necessary	\$ 100.00	\$ 85.00 <i>30</i>
1	Rear windscreen sealant	Necessary	\$ 100.00	\$ 60.00 <i>40</i>
1	Rear reverse sensor (1 set)	Damage	\$ 350.00	\$ 280.00 <i>200</i>
			\$ 550.00	\$ 425.00

Spare Parts Total \$ 9837.86 \$ 7263.50

Vehicle No: **SNC 375 L**
 Report No: **TP/ 24012-07/MY / 2024**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 9837.86	\$ 7263.50
1	To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts.	\$ 70.00	\$ 50.00 20
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 220.00	\$ 140.00 60
3	To remove and refit rear bumper sensor.	\$ 150.00	\$ 80.00 30
4	To remove and refit rear windscreen glass.	\$ 220.00	\$ 150.00 120
5	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1800.00	\$ 1500.00 1200
6	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1600.00	\$ 1250.00 1080
7	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 200.00	\$ 120.00 90
Total		<u>\$ 14097.86</u>	<u>\$ 10553.50</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 8400.00

SDLS: EIGHT THOUSAND FOUR HUNDRED ONLY


 Qualified Appraiser

P. 4730/11
 202
 3784.09
 270
 2600.