

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9, Singapore 539278
TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
GST:52832105J RCB NO:201327339E

not Authorized
her
means
18/9/24
2/5 \$5300
3 days
The phr-Attny-

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909
TEL: - FAX: -
ATTN: Motor Claim Department

Estimate No: ES1602147
Date: 24 Aug 2024
Policy No: SP2031439637
Veh Reg No: XE9333U
Make/Model: MITSUBISHI FUSO
FV51SJD2DEA
Chassis No: FV51SJA20125
Engine No: OM457LA457972C033067
Reg. Date: 01/03/2017

Your Ref No: MAJESTIC CIVIL ENG
Claim Type: Third Party
Accident Date: 24/08/2024
TP Veh Reg No: SNN4769A

Estimate Repair Cost to Vehicle No :XE9333U

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 Front Bumper	2,259.31	1 PC	2,259.31	✓
2 Front Bumper Cover -LH	305.89	1 PC	305.89	X
3 Front Bumper Side -LH	140.29	1 PC	140.29	✓
4 Front Bumper Step Garnish	217.26	1 PC	217.26	X
5 Front Bumper Lower Stay	169.07	2 PC	338.14	X
6 Front Bumper Bracket	37.30	1 PC	37.30	X
7 Front Bumper Side Air Dust -LH	96.70	1 PC	96.70	✓
8 Front Top Bumper	273.12	1 PC	273.12	X
9 Front Top Bumper Reinforcement	884.79	1 PC	884.79	X
10 Front Top Bumper -LH	193.04	1 PC	193.04	X
11 Front Top Bumper Reinforcement -LH	226.06	1 PC	226.06	X
12 Front Headlamp Assy -LH	1,286.45	1 PC	1,286.45	✓
13 Front Headlamp Rim -LH	181.18	1 PC	181.18	✓
14 Front Headlamp Aluminium Bracket -LH	947.63	1 PC	947.63	✓
15 Front Fog Lamp Assy -LH	293.25	1 PC	293.25	✓
16 Front Fog Lamp Rim -LH	186.05	1 PC	186.05	✓
17 Front Door Lamp -LH	195.03	1 PC	195.03	✓
18 Stand Panel -LH	744.59	1 PC	744.59	✓
19 Stand Panel Alloy Mat Centre -LH	289.84	1 PC	289.84	X
20 Stand Panel Side Bracket -LH	254.70	1 PC	254.70	X
21 Step Panel -LH	324.55	1 PC	324.55	✓
22 Step Panel Lower -LH	270.56	1 PC	270.56	✓
23 Step Panel Under Cover -LH	229.87	1 PC	229.87	X
24 Step Panel Reflector -LH	123.45	1 PC	123.45	X
25 Step Alloy Mat -LH	326.00	1 PC	326.00	✓
26 Step Holder Front -LH	875.91	1 PC	875.91	X
27 Step Holder Rear -LH	629.25	1 PC	629.25	X
			12,130.21	
		Less 25%	3,032.55	9,097.69
Labour				
28 To remove & refit headlamp cable ,system & check wiring & refocus all light .	230.00	1 -	230.00	20
29 Labour charge to cut & weld & dismantle & remove & refit all above parts .	2,000.00	1 -	2,000.00	600
30 To rust proofing on affected area .	850.00	1 -	850.00	X
31 To spray & painting all accident affected area (Metalic Colour)	1,800.00	1 -	1,800.00	600

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9, Singapore 539278
TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
GST:52832105J RCB NO:201327339E

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 Anson Road
#15-00 Springleaft Tower
Singapore 079909
TEL: - FAX: -
ATTN: Motor Claim Department

Your Ref No: MAJESTIC CIVIL ENG
Claim Type: Third Party
Accident Date: 24/08/2024
TP Veh Reg No: SNN4769A

Estimate No: ES1602147
Date: 24 Aug 2024
Policy No: SP2031439637
Veh Reg No: XE9333U
Make/Model: MITSUBISHI FUSO
FV51SJD2DEA
Chassis No: FV51SJA20125
Engine No: OM457LA457972C033067
Reg. Date: 01/03/2017

Estimate Repair Cost to Vehicle No :XE9333U

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
			4,880.00	4,880.00
Total				S\$ 13,977.69
Add GST @ 9%				1,257.99
Total Amount Payable				S\$ 15,235.68

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND TWO HUNDRED THIRTY FIVE AND CENTS SIXTY EIGHT ONLY

**For HUP LIAN HUAT ENGINEERING
WORKS**

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-7281.59
252
5428.69
1220
6658.69
202
5326.