9/9/24, 10:28 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24080502/ENP3E2

**Date:** 09/09/2024

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MAA00606

Claimant Vehicle

SHA9922K

Insured Vehicle No: SME50959

No: SHA8833K Insured Vehicle No: SME5085S

Date of Loss: 28/08/2024 Nature of Claim: TP Claim No: M2404933

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHA8833K

Make & Model: TOYOTA PRIUS TAXI, 1.8 HATCHBACK(AT) Engine No: 2ZRS061516

Reg. Date: 12/07/2017 (Man. Year: 2017) Chassis No: JTDKB3FU503559427

Colour: Yellow Odometer: 109229 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm
West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,904.99	1,165.00	739.99	38.84
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,260.00	680.00	580.00	46.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,176.99	1,857.00	1,319.99	41.55
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	3,176.99	1,500.00	1,676.99	52.79
+ GST 9.00/9.00% (S\$)	285.93	135.00	150.93	52.79
Nett Amount (S\$)	3,462.92	1,635.00	1,827.92	52.79

**INSPECTION** 

Date of Assignment: 29/08/2024 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 29/08/2024 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Sep 2024)

Parts: 144 TOYOTA PRIUS TAXI 1.8 HATCHBACK(AT)(2WD) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHA8833K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	503.04 FL	*503.04 FL
2	1		*REAR BUMPER LOWER COVER	Cut	654.96 FL	*654.96 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	378.32 FL	*- FL
4	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	82.70 FL	*- FL
5	1		*REAR BUMPER RETAINER LH	Not Necessary	112.70 FL	*- FL
6	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
7	1		*REAR BUMPER LOWER SEAL LH	Repair	232.00 FL	*- FL
8	1		*REAR BUMPER ADVERTISEMENT	Necessary	80.00 FS	*80.00 FS
9	2		*REAR FENDER LH & RH ADVERTISEMENT	Necessary	200.00 FS	*200.00 FS
10	1		*REAR REVERSE SENSOR	Not Necessary	135.70 FS	*-FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.			
				Sub Total (S\$)	2,401.42	1,460.00
			- List Item Discount or	L Items 25.00/25.00% (S\$)	496.43	295.00
				Total Parts (S\$)	1,904.99	1,165.00
				_		

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount			
Mis	Miscellaneous Items							
1	1	OD/TP Case (Insurer)		12.00	12.00			
			Sub Total (S\$)	12.00	12.00			

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	750.00	380.00
2	SPRAY PAINTING	New	450.00	280.00
3	REMOVE /REFIX REVERSE SENSOR	New	60.00	20.00
		Gross Labour Cost (S\$)	1,260.00	680.00
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >