

Smm348A.

Rear Bumper	Distorted ✓	865	✓	Rear Bumper Under Cover Side	nec
	Clips. in	30(SW)			45
	Side Holder. could	42	✓		
	Reflector	could	40		
	Inner Side Garish.	Distorted	58	✓	
Rear End Panel	Distorted	750	✓		
	Top Garish	Distorted	210	✓	
	Clips	in	30(SW)	✓	
	Sealant.	in	60(SW)	✓	
Taillamp	Smashed	530	✓		
Panel	Repair	215	+		
Lower Bracket	Could	45	✓		
Tailgate	Distorted	1210	✓		
Lock	and	180	✓		
Weatherstripe. Cut		170	✓		
Inner Trim Board	could	315	✓		
	Clips. in	30(SW)	✓		
Outer Moulding	could	340	✓		
	Clips. in	30(SW)	✓		
Lamp	Smashed	395	✓		

SMM 348A.

Tailgate Surround Moulding. *rev* 80(SN) ✓

Tailgate Glass Moulding *rev* 125 ✓

Sealant. *rev* 60(SN) ✓

Honda Logo } 40 ✓

Freeed Wordings } ~~100~~ 50 ✓

Hybrid Emblem. } 55 ✓

Rear Fender *Revis* 985 +

Inner Trim Board *Revised* 390 ✓

lip *rev* 30(SN) ✓

Reverse Sensor *Rev* 200(SN) ✓

Panel Bunting 800

Spray Painting 800.

Wiring 30

To spray full coat 60

To remove upholstery 60

To remove reverse sensor 50

To transfer tailgate fitting 60

To remove tailgate glass 120

To remove rear camera 50

To remove video recorder 50.

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: