7/9/24, 3:24 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24060134/TVH3M4

**Date:** 09/07/2024

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MAB00160

Claimant Vehicle Curpocoom Control of the Control

No: Insured Vehicle No: GBL6591J

Date of Loss: 13/06/2024 Nature of Claim: TP Claim No: M2403328

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHD8630M

Make & Model: HYUNDAI AE IONIQ HEV, 1.6 DCT (A) Engine No: G4LEJU131996

Reg. Date: 04/12/2018 (Man. Year: 2018) Chassis No: KMHC851CVKU121782

Colour: Yellow Odometer: 360765 km

Engine Capacity: 1580 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

**CONDITION OF TYRES** 

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS              | Repairer's          | Adjuster's | Difference | Diff % |
|-----------------------------|---------------------|------------|------------|--------|
| Parts                       | 3,274.88            | 357.12     | 2,917.76   | 89.10  |
| Miscellaneous Items         | 12.00               | 12.00      | 0.00       | 0.00   |
| Labour                      | 2,150.00            | 1,355.00   | 795.00     | 36.98  |
| Paintwork Labour            | 0.00                | 0.00       | 0.00       |        |
| Towing                      | 0.00                | 0.00       | 0.00       |        |
| Calculated Gross Total (    | (S\$) 5,436.88      | 1,724.12   | 3,712.76   | 68.29  |
| Approved Total (Overridden) | (S\$)               | 1,350.00   |            |        |
|                             | (\$\$) 5,436.88     | 1,350.00   | 4,086.88   | 75.17  |
| + GST 9.00/9.00% (          | <b>(S\$)</b> 489.32 | 121.50     | 367.82     | 75.17  |
| Nett Amount                 | (S\$) 5,926.20      | 1,471.50   | 4,454.70   | 75.17  |

**INSPECTION** 

Date of Assignment: 18/06/2024 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

COMFORTDELGRO ENGINEERING PTE LTD

Date Inspected: 18/06/2024 Inspected At: 59 LOYANG DRIVE

SINGAPORE 508969

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/9/24, 3:24 PM Adjuster Report

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Jul 2024)

Parts: 143 HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD8630M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

| No.   | Qty  | Part No.     | Particulars                        | Condition         | Repairer's  | Amount     |
|-------|--|--------------|------------------------------------|-------------------|-------------|------------|
| 1     | 1  |              | *1 REAR BUMPER                     | Repair            | 459.40 FL   | *- FL      |
| 2     | 1  |              | *1 REAR BRACKET RH                 | Not Necessary     | 55.80 FL    | *- FL      |
| 3     | 1  |              | *1 REAR FENDER RH                  | Repair            | 588.80 FL   | *- FL      |
| 4     | 1  |              | *1 REAR DOOR RH                    | Repair            | 2,147.90 FL | *- FL      |
| 5     | 1  |              | *1 REAR WHEEL RIM COVER RH         | Cut               | 346.40 FL   | *346.40 FL |
| 6     | 1  |              | *1 REAR DOOR MOULDING RH           | Repair            | 125.30 FL   | *- FL      |
| 7     | 1  |              | *1 ROCKER GARNISH RH               | Repair            | 270.00 FL   | *- FL      |
| 8     | 1  |              | *REAR DOOR COMFORT ZIG APP STICKER | Necessary         | 80.00 FS    | *80.00 FS  |
| F=Fra | ınchise  | part. S=SpcN | ett. L=ListItemDisc.               | _                 |             |            |
|       |  |              |                                    | Sub Total (S\$)   | 4,073.60    | 426.40     |
|       | - List Item Discount on L Items 20.00/20.00% (S\$) |              |                                    | 798.72            | 69.28       |            |
|       |  |              |                                    | Total Parts (S\$) | 3,274.88    | 357.12     |

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

| No  | Qty                 | Particulars          |                 | Repairer's | Amount |  |  |  |
|-----|---------------------|----------------------|-----------------|------------|--------|--|--|--|
| Mis | Miscellaneous Items |                      |                 |            |        |  |  |  |
| 1   | 1                   | OD/TP Case (Insurer) |                 | 12.00      | 12.00  |  |  |  |
|     |                     |                      | Sub Total (S\$) | 12.00      | 12.00  |  |  |  |

## Recommended Labour

| Particulars                   | Lab.Type   | Repairer's   | Amount  |
|-------------------------------|--|--|---|
| our Items                     |  |  |   |
| PANEL BEATING                 | New  | 1,200.00   | 525.00  |
| SPRAY PAINTING                | New  | 800.00   | 800.00  |
| REMOVE/ REFXI REAR UPHOLSTERY | New  | 90.00  | 0.00  |
| REMOVE/REFIX REVERSE SENSOR   | New  | 60.00  | 30.00   |
|                               | Gross Labour Cost (S\$)  | 2,150.00   | 1,355.00  |
|                               | our Items PANEL BEATING SPRAY PAINTING REMOVE/ REFXI REAR UPHOLSTERY | PANEL BEATING New SPRAY PAINTING New REMOVE/ REFXI REAR UPHOLSTERY New REMOVE/REFIX REVERSE SENSOR New | DUIT Items           PANEL BEATING         New         1,200.00           SPRAY PAINTING         New         800.00           REMOVE/ REFXI REAR UPHOLSTERY         New         90.00           REMOVE/REFIX REVERSE SENSOR         New         60.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >