

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080511/UMA3Q2
Date: 15/11/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MCV0005568_02
Claimant Vehicle No : YN1685Y Insured Vehicle No : PC8973J
Date of Loss: 15/08/2024 Nature of Claim: TP Claim No: MCV2024D0009480

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YN1685Y
Make & Model: HINO GH8JRKA, 7.7 D (M) Engine No: J08EUB13100
Reg. Date: 29/11/2010 (Man. Year: 2010) Chassis No: GH8JRK12383
Colour: White Odometer: 385604 km
Engine Capacity: 7684 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 10.00 R20 Rear Tyre Size: 10.00 R20 (D)
Front Left Side: Austone 5 mm Rear Left Side: Austone 5/5 mm
Front Right Side: Austone 5 mm Rear Right Side: Austone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	650.00	300.00	350.00	53.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	200.00	400.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,250.00	500.00	750.00	60.00
+ Loss of Use (2.0 x S\$130.00/day) (S\$)		260.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		762.18		
Global Sum Settlement (S\$)		760.00		

INSPECTION

Date of Assignment: 29/08/2024
Date Inspected: 29/08/2024 Inspected At: Liu's Brother Auto Engineering Workshop (HQ)
KAKI BUKIT
Singapore 417883
Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Nghiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Oct 2024)	
Parts:	N/A	HINO GH8JRKA 7.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN1685Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH POWERGATE PANEL	Cracked	650.00 FS	*300.00 FS
						F=Franchise part. S=SpcNett.
Total Parts (S\$)					650.00	300.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	300.00	200.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	300.00	0.00
Gross Labour Cost (\$\$)			600.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >