LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21001397/QPA3Q2

06/12/2021 Date:

REFERENCE

AIG Asia Pacific Handling Insurer:

Insurance Pte. Ltd.

Policy No: 2070164204

Claimant Vehicle

SMB1425L

Insured Vehicle

No:

No:

SFA1778G

Date of Loss:

22/01/2021

Nature of Claim:

ΤP

Claim No:

537647 km

50337640243765

WMAA22ZZXE7002139

5301238076SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Make & Model: Reg. Date:

MAN NL320F (A22), 10.5 D ABS TURBO (A)

08/07/2014 (Man. Year: 2014)

Multi-colour

Engine Capacity: Market Value/New Car 10518 cc N/A

Price:

Colour:

Sum Insured (S\$): Market Value/New Car Price

SMB1425L

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable): Yes

Pre-accident Condition:

Yes

Handbrake (Serviceable): **Engine Modification:** Yes

CONDITION OF TYRES

Front Tyre Size: Front Left Side: Front Right Side: 275/70 R22.5 Falken 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side:

Engine No:

Chassis No:

Nο

Odometer:

275/70 R22.5 Falken 6 mm Falken 6 mm

Falken 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,027.20	960.00	2,067.20	68.29
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,768.00	1,068.00	700.00	39.59
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	4,795.20	2,028.00	2,767.20	57.71

+ Loss of Use (2.0 x S\$250.00/day) (S\$) 500.00 + Doc/Search Fee (S\$) 7.00

> **Nett Liability (S\$)** 2,535.00

INSPECTION

Date Inspected:

Date of Assignment:

29/01/2021

28/01/2021 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ,SIDE:L11 ,FOR MAN A22 BUS	Repair	1,092.50 F	*- F
2	1		*COVER :REAR TAIL LAMP ,LH,FOR MAN A22 BUS	Repair	974.70 F	*- F
3	1		*ADVERTISEMENT STICKER	Necessary	960.00 FS	*960.00 FS
F=Frai	nchise p	art. S=SpcNe	ett.	Total Parts (S\$)	3,027.20	960.00
LKK Auto Consultants Pto Ltd/SMR1/25L/06/12/2021 10:33						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	Labour Items								
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,060.00	530.00					
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	708.00	538.00					
	Gross Labour Cost (S\$)		1,768.00	1,068.00					
	LKK Auto Consultants Pte Ltd/SMB1425L/06/	12/2021 10:33							

< END OF ESTIMATES >