

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090009/UPA3Q2
Date: 05/12/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MPC0002651_01
Claimant Vehicle No : SNG9810S Insured Vehicle No : SLN4888M
Date of Loss: 29/08/2024 Nature of Claim: TP Claim No: MPC2024D0010226

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNG9810S
Make & Model: BYD E6 (ME-2), (A) Engine No: HIDDEN
Reg. Date: 20/09/2022 (Man. Year: 2022) Chassis No: LC0CE4DC8N0090392
Colour: Blue Odometer: 284969 km
Engine Capacity: 0 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55Z R17 Rear Tyre Size: 215/55Z R17
Front Left Side: DERUIBO 6 mm Rear Left Side: ZEXTOUR 6 mm
Front Right Side: DERUIBO 6 mm Rear Right Side: ZEXTOUR 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,241.77	6,290.51	13,951.26	68.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	970.00	2,780.00	74.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,991.77	7,260.51	16,731.26	69.74
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	23,991.77	5,800.00	18,191.77	75.83
+ GST 9.00/9.00% (S\$)	2,159.26	522.00	1,637.26	75.83
Nett Amount (S\$)	26,151.03	6,322.00	19,829.03	75.83
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		6,589.25		

INSPECTION

Date of Assignment: 02/09/2024
Date Inspected: 02/09/2024 Inspected At: Carsmith Private Limited (HQ)
8 Kaki Bukit Ave 4, #04-35 Premier
Singapore 415875
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2024)
Parts:	M1-MPV	BYD E6 (ME-2) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNG9810S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent / Buckled	2,695.68 FL	*2,695.68 FL
2	1		*FRONT BONNET INSULATOR	Not Necessary	565.00 FL	*- FL
3	1		*FRONT BONNET LOCK	Not Necessary	475.00 FL	*- FL
4	2		*FRONT BONNET HINGE	Not Necessary	290.00 FL	*- FL
5	1		*FRONT BUMPER	Deformed / Torn	3,062.40 FL	*1,258.00 FL
6	1		*FRONT BUMPER RETAINER LH	Not Necessary	79.00 FL	*- FL
7	1		*FRONT BUMPER RETAINER RH	Not Necessary	79.00 FL	*- FL
8	1		*FRONT BUMPER BRACKET LH	Not Necessary	79.00 FL	*- FL
9	1		*FRONT BUMPER BRACKET RH	Not Necessary	79.00 FL	*- FL
10	1		*FRONT BUMPER CENTER CHROME	Scratched	825.00 FL	*358.00 FL
11	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	275.00 FL	*- FL
12	1		*FRONT BUMPER LOWER GRILLE LH	Not Necessary	285.00 FL	*- FL
13	1		*FRONT BUMPER LOWER GRILLE RH	Not Necessary	285.00 FL	*- FL
14	1		*FRONT REINFORCEMENT	Repair	668.00 FL	*- FL
15	1		*FRONT SUPPORT PANEL	Repair	1,785.00 FL	*- FL
16	1		*FRONT HEADLAMP LH	Cracked	3,250.00 FL	*2,600.00 FL
17	1		*FRONT HEADLAMP PANEL LH	Repair	325.00 FL	*- FL
18	1		*FRONT HEADLAMP BRACKET LH	No such part	179.00 FL	*- FL
19	1		*FRONT HEADLAMP RH	Not Necessary	3,250.00 FL	*- FL
20	1		*FRONT HEADLAMP PANEL RH	Not Necessary	325.00 FL	*- FL
21	1		*FRONT HEADLAMP BRACKET RH	Not Necessary	179.00 FL	*- FL
22	1		*FRONT FENDER LH (DENTED)	Not Consistent With The Impact	2,550.00 FL	*- FL
23	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	528.00 FL	*- FL
24	1		*SET FRONT NUMBER PLATE	Bent	90.00 FS	*40.00 FS
25	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
26	1		*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	100.00 FS	*- FS
27	1		*JOINT SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,453.08	6,981.68
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,211.31	691.17
Total Parts (\$\$)	20,241.77	6,290.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	New	200.00	20.00
2	REMOVE AND REFIT FRONT ACCIDENT AFFECTED AREA LINING TRIM AND GARNISH	New	450.00	0.00
3	PANEL BEATING ON AFFECTED AND RENEW DAMAGE PARTS	New	1,500.00	420.00
4	SPRAY PAINTING ON AFFECTED AREAS	New	1,500.00	500.00
5	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	30.00
Gross Labour Cost (\$\$)			3,750.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >