



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMW 5303T

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR N/S TAIL-LAMP	CUT	\$480.00	\$480.00
1	REAR BUMPER	MTG CRACKED	\$688.00	\$612.20
1	REAR N/S BUMPER SIDE RETAINER	SERVICEABLE	\$55.00	\$0.00
	LESS 10.00% DISCOUNT		(\$122.30)	(\$109.22)
			\$1,100.70	\$982.98
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING		\$500.00	\$200.00
	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION		\$500.00	\$400.00
	CHECK/RECONNECT WIRING		\$30.00	\$20.00
			\$1,030.00	\$620.00
GRAND TOTAL			\$2,130.70	\$1,602.98
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,250.00
Report Ref No: CS/FCI24090012/Knp3m4				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.