

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090013/KMA3Q2**Date:** 17/06/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7240053740
Claimant Vehicle No : GBG1705H **Insured Vehicle No :** GBA1902L
 Date of Loss: 30/08/2024 Nature of Claim: TP Claim No: 0392883302SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG1705H**
 Make & Model: TOYOTA HIACE, 3.0 D DX (M) Engine No: 1KD2676027
 Reg. Date: 15/06/2017 (Man. Year: 2016) Chassis No: KDH2015025199
 Colour: Silver Odometer: 232948 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 195 R15X8
 Front Left Side: Toyo 9 mm Rear Left Side: Toyo 9 mm
 Front Right Side: Toyo 9 mm Rear Right Side: Toyo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,215.77	5,730.35	2,485.42	30.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	770.00	380.00	33.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,365.77	6,500.35	2,865.42	30.59
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	9,365.77	5,200.00	4,165.77	44.48
+ GST 9.00/9.00% (S\$)	842.92	468.00	374.92	44.48
Nett Amount (S\$)	10,208.69	5,668.00	4,540.69	44.48
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		5,990.18		

INSPECTION

Date of Assignment: 09/09/2024
 Date Inspected: 09/09/2024 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Estimated Period of Repair: 4.0 days Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761

Adjuster: KENNETH KONG**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Cut	836.90 FL	*836.90 FL
2	1		*FRONT BUMPER RH RETAINER	Cracked	126.10 FL	*126.10 FL
3	6		*FRONT BUMPER CLIPS	Necessary	27.00 FL	*27.00 FL
4	1		*FRONT RH STEP TRAY	Cut	224.70 FL	*224.70 FL
5	1		*FRONT RH WIPER SIDE GARNISH EXTENSION	Cut	48.70 FL	*48.70 FL
6	1		*HEADLAMP RH	Cut	3,967.50 FL	*3,967.50 FL
7	1		*FRONT RH DOOR	Repair	2,904.60 FL	*- FL
8	1		*FRONT RH DOOR GLASS	Cut	746.80 FL	*746.80 FL
9	1		*FRONT RH DOOR GLASS OUTER MOULDING	Dented	128.60 FL	*128.60 FL
10	1		*FRONT RH SIDE MIRROR	Broken	1,507.50 FL	*1,507.50 FL
11	1		*FRONT RH CORNER PANEL	Repair	409.30 FL	*- FL
12	1		*FRONT RH DOOR COMPANY STICKER	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,947.70	7,633.80
- List Item Discount on L Items 25.00/25.00% (\$)	2,731.93	1,903.45
Total Parts (\$)	8,215.77	5,730.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	450.00
2	REMOVE AND REFIT FRT RH DOOR GLASS	New	50.00	0.00
3	PUTTY AND RESPRAY ON FRTRH CORNER PANEL ,FRT RH DOOR AND SIDE MIRROR	New	500.00	320.00
Gross Labour Cost (\$\$)			1,150.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >