

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24090014/UMA3Q2**Date:** 06/12/2024**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000046
<b>Claimant Vehicle No :</b>	SLD3903L	<b>Insured Vehicle No :</b>	SLL5259H
Date of Loss:	28/08/2024	Nature of Claim:	TP
		Claim No:	8815868258SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLD3903L</b>	Engine No:	6ARP178213
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	MR053DK5100107273
Reg. Date:	15/06/2016 (Man. Year: 2016)	Odometer:	178465 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,808.00	5,253.65	2,554.35	32.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,255.00	1,970.00	2,285.00	53.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,063.00</b>	<b>7,223.65</b>	<b>4,839.35</b>	<b>40.12</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,063.00</b>	<b>5,700.00</b>	<b>6,363.00</b>	<b>52.75</b>
<b>+ Car Rental (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		27.25		
<b>Nett Liability (S\$)</b>		<b>6,227.25</b>		
<b>Global Sum Settlement (S\$)</b>		<b>6,200.00</b>		

**INSPECTION**

Date of Assignment:	02/09/2024		
Date Inspected:	02/09/2024	Inspected At:	Wheelz 4 you (HQ) 9002 Tampines St 93, #01-72 Singapore 528836
Estimated Period of Repair:	5.0 days		

**Adjuster:** MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH REAR DOOR	Dented / Bent	1,450.00 FL	*1,450.00 FL
2	1		*RH REAR DOOR TAPE	Necessary	138.00 FL	*60.00 FL
3	1		*RH REAR DOOR WEATHERSTRIP	Not Necessary	259.00 FL	*- FL
4	1		*RH REAR DOOR LOCK	Not Necessary	651.00 FL	*- FL
5	1		*RH SIDE SKIRT	Cut / Torn	590.00 FL	*590.00 FL
6	1		*RH REAR FENDER	Repair	869.00 FL	*- FL
7	1		*RH REAR FENDER INNER SHIELD	Not Necessary	311.00 FL	*- FL
8	1		*REAR BUMPER	Cut / Torn	723.00 FL	*723.00 FL
9	1		*RH REAR BUMPER SIDE RETAINER	Not Necessary	143.00 FL	*- FL
10	1		*RH REAR RIM	Cut	1,976.00 FL	*1,600.00 FL
11	1		*RH REAR SHOCK ABSORBER	Bent	404.00 FL	*392.00 FL
12	1		*RH REAR WHEEL BEARING	Damaged	633.00 FL	*633.00 FL
13	1		*REAR WINDSCREEN MOULDING	Not Necessary	198.00 FL	*- FL
14	1		*RH WING MIRROR	Cracked / Damaged	1,639.00 FL	*1,450.20 FL
15	1		*RH REAR DOOR INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
16	1		*RH REAR FENDER INNER SHIELD CLIP	Not Necessary	40.00 FS	*- FS
17	1		*RH SIDE SKIRT CLIP	Necessary	40.00 FS	*40.00 FS
18	1		*REAR BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
19	1		*REAR BUMPER RIVET	Not Necessary	40.00 FS	*- FS
20	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
21	1		*REAR WINDSCREEN SEALANT	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>10,304.00</b>	<b>6,978.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	2,496.00	1,724.55
<b>Total Parts (\$)</b>	<b>7,808.00</b>	<b>5,253.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK REAR PORTION WIRING	New	50.00	20.00
2	TO FRT REVERSE SENSOR ON NEW BUMPER	New	50.00	30.00
3	TO RESET PDC	New	350.00	0.00
4	TO TRANSFER RH REAR DOOR GLASS }	New	120.00	50.00
5	TO TRANSFER RH REAR DOOR MECHANISM }	New	120.00	0.00
6	TO RE-CALIBRATE RH REAR CENTRAL LOCKING }	New	25.00	0.00
7	TO RE-CALIBRATE RH REAR POWER WINDOW	New	250.00	0.00
8	TO TRANSFER RH REAR TYRE ON NEW RIM PLUS BALANCING	New	50.00	0.00
9	TO REPLACE RH REAR UNDERCARRIAGE	New	350.00	150.00
10	TO CONDUCT 4 WHEEL ALIGNMENT	New	120.00	80.00
11	TO REMOVE/REFIX REAR WINDSCREEN	New	120.00	0.00
12	TO REMOVE /REFIX INNER TRIM ,GARNISHES TO FACILITATE REPAIR	New	250.00	60.00
13	TO PANEL BEAT AND REPLACEMENT OF PARTS	New	1,200.00	580.00
14	TO PUTTY AND SPRAY PAINT ACCIDENT DAMAGE AREA	New	1,200.00	1,000.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,255.00</b>	<b>1,970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >