## FAR EAST TYRES && BATTERIES TRADING BLOCK 9002 TAMPINES STREET 93

#01-32 528836 SINGAPORE

TEL: 67851902 FAX: 67494328

Work Order:

R001553


VIN: Date SLD3903L 2.9.24 17:25





Toyota: Camry/Aurion: ASV70 GSV70 AXVA70 (2017.9-2017.12): ASV70 AXVA70 (except Rough Road Suspension): with 205/65R16, 215/55R17 Tire

4-Wheel Total Alignment

**Current Measurements** 











Negative Camber could cause road shock or poor ride quality.


Excessive Toe causes scuffing, shoulder wear and poor fuel economy.


Negative Caster could cause reduced directional stability.

Negative Caster could cause reduced returnability.













- Excessive Camber causes shoulder wear and poor handling.
- · Excessive Toe causes scuffing, shoulder wear and poor fuel economy.



This vehicle's Steering Angle Sensor may require calibration using an OEM scan tool after alignment.