9/11/24, 10:08 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III24090018/KQP3E2

**Date:** 11/09/2024

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MCV0008228

Claimant Vehicle SMS2654X Insured Vehicle No: PC4724M

No:

Date of Loss: 29/08/2024 Nature of Claim: TP Claim No: MCV2024D0010334

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMS2654X

Make & Model:HONDA SHUTTLE HYBRID, 1.5 (A)Engine No:LEB7103305Reg. Date:19/02/2020 (Man. Year: 2018)Chassis No:GP72002496Colour:Metallic GreyOdometer:365278 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Davanti 8 mm Rear Left Side: Davanti 8 mm
Front Right Side: Davanti 8 mm Rear Right Side: Davanti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		14,961.32	4,867.01	10,094.31	67.47
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,050.00	1,440.00	610.00	29.76
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	17,011.32	6,307.01	10,704.31	62.92
	Approved Total (Overridden) (S\$)		5,000.00		
	Nett Amount (S\$)	17,011.32	5,000.00	12,011.32	70.61

**INSPECTION** 

Date of Assignment: 02/09/2024

Jd Motorsports Pte Ltd (HQ)

Date Inspected: 02/09/2024 Inspected At: 25 KAKI BUKIT ROAD 4, #05-76 Synergy@KB

Singapore 417800

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 11 Sep 2024)

Parts: N/A HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMS2654X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	2,291.40 F	*1,050.60 FL
2	1		*REAR RH BUMPER REFLECTOR GANISH	Serviceable	177.36 F	*- FL
3	1		*REAR RH BUMPER REFLECTOR	Serviceable	163.20 F	*- FL
4	1		*REAR BUMPER TOWING COVER	Serviceable	42.84 F	*- FL
5	1		*REAR BUMPER SIDE RETAINER	O/S Distorted	243.90 F	*64.00 FL
6	1		*REAR BUMPER RH INNER SIDE PROTECTOR	Serviceable	65.28 F	*- FL
7	1		*REAR BUMPER MOULDING	No such part	219.60 F	*- FL
8	1		*REAR BUMPER INNER BRACKET	Repair	60.06 F	*- FL
9	1		*REAR END PANEL	Bent	854.30 F	*681.20 FL
10	1		*REAR END PANEL TOP GANISH	Dented	236.10 F	*236.10 FL
11	1		*REAR TAIL GATE WEATHERSTRIP (\$166.50) (50%)	Distorted / Dented	299.46 FS	*83.25 FS
12	1		*REAR TAIL GATE	Bent	2,522.22 F	*1,193.20 FL
13	1		*REAR TAIL GATE OUTER GANISH	Serviceable	387.85 F	*- FL
14	1		*REAR TAIL GATE OUTER CHROME GANISH	Cracked	286.30 F	*286.30 FL
15	1		*REAR TAIL GATE EMBLEM LOGO	Necessary	125.70 F	*98.70 FL
16	1		*REAR TAIL GATE EMBLEM SHUTTLE	Necessary	145.20 F	*92.50 FL
17	1		*REAR TAIL GATE EMBLEM HYBRID	Necessary	105.60 F	*94.30 FL
18	1		*REAR TAIL GATE OUTER HANDLE	Serviceable	165.40 F	*- FL
19	2		*REAR TAIL GATE NUMBER PLATE LAMP	Serviceable	196.80 F	*- FL
20	1		*REAR RH TAIL LAMP	Cracked	943.05 F	*592.30 FL
21	1		*REAR RH TAIL GATE LAMP	Cracked	891.08 F	*580.90 FL
22	1		*REAR TAIL GATE INNER TRIM BOARD	Buckled / Dented	781.60 F	*320.60 FL
23	1		*REAR WIPER MOTOR	Serviceable	732.60 F	*- FL
24	2		*REAR TAIL GATE ABSORBER	Serviceable	598.92 F	*- FL
25	1		*REAR TAIL GATE INNER LOCK	Repair	456.85 F	*- FL
26	1		*REAR TAIL GATE CATCH HOOK	Repair	96.30 F	*- FL
27	1		*REAR TAIL GATE INNER HANDLE	Serviceable	93.35 F	*- FL
28	2		*REAR TAIL GATE STOPPER	Serviceable	50.00 F	*- FL
29	1		*FENDER INNER TRIM BOARD RH REAR	Mtg Cracked	489.00 F	*489.00 FL
30	10		*DOOR TRIM BOARD CLIP	Necessary	80.00 FS	*80.00 FS
31	2		*PARKING SENSOR	Serviceable	500.00 FS	*- FS
32	1		*REAR PARKING CAMERA	Serviceable	520.00 FS	*- FS
33	5		*REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
34	1		*WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

 Sub Total (S\$)
 14,961.32
 6,022.95

 - List Item Discount on L Items 0.00/20.00% (S\$)
 0.00
 1,155.94

**Total Parts (S\$)** 

. . .

14,961.32

4,867.01

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	New	800.00	700.00
2	TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	New	600.00	600.00
3	TO SUPPLY LABOUR TO DISMANTLE & REFIT REAR WINDSCREEN	New	300.00	120.00
4	TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	New	100.00	20.00
5	TO SUPPLY COMPUTER DIANOGTIC	New	250.00	0.00
	Gross Labou	ır Cost (S\$)	2,050.00	1,440.00
	Report was unsubmitted during this pr	int-out.		

< END OF ESTIMATES >