

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24090019/KVP3E2**Date:** 23/09/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30003855029		
Claimant Vehicle No :	SMX2889J	Insured Vehicle No :	YQ8616K		
Date of Loss:	02/09/2024	Nature of Claim:	TP	Claim No:	371861

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX2889J	Engine No:	G4FMLU208877
Make & Model:	HYUNDAI CN7 AVANTE, 1.6 DOHC CVT S (A)	Chassis No:	KMHLN41ETMU111824
Reg. Date:	05/01/2021 (Man. Year: 2020)	Odometer:	45797 km
Colour:	Metallic Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,837.60	5,687.04	3,150.56	35.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,840.00	1,460.00	1,380.00	48.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,677.60	7,147.04	4,530.56	38.80
Approved Total (Overridden) (\$\$)		5,700.00		
Nett Amount (\$\$)	11,677.60	5,700.00	5,977.60	51.19

INSPECTION

Date of Assignment:	02/09/2024		
Date Inspected:	03/09/2024	Inspected At:	Massive Trading & Auto Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2 Singapore 569541
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Sep 2024)
Parts:	143	HYUNDAI CN7 AVANTE 1.6 DOHC CVT S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX2889J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	2,073.00 FL	*2,073.00 FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	115.00 FL	*115.00 FL
3	1		*REAR BOOT LID INNER LOCK	Dented	185.00 FL	*185.00 FL
4	1		*REAR BOOT LID EMBLEM LOGO	Necessary	65.00 FL	*65.00 FL
5	1		*REAR BOOT LID EMBLEM AVANTE	Necessary	75.00 FL	*75.00 FL
6	1		*REAR BOOT LID TOP COVER	Serviceable	499.00 FL	*- FL
7	1		*REAR BOOT LID REFLECTOR	Cracked	1,052.00 FL	*1,052.00 FL
8	2		*REAR TAIL-LAMP ASSY	Serviceable	1,750.00 FL	*- FL
9	1		*REAR BOOT RUBBER	Dented / Distorted	165.00 FL	*165.00 FL
10	1		*REAR END PANEL	Bent	485.00 FL	*485.00 FL
11	1		*REAR END PANEL INNER GARNISH	Serviceable	184.00 FL	*- FL
12	1		*REAR N/S FENDER INNER TRIM BOARD	Serviceable	311.00 FL	*- FL
13	1		*REAR BUMPER	Buckled	499.00 FL	*499.00 FL
14	1		*REAR BUMPER LOWER GARNISH	Dented / Cut	394.00 FL	*341.00 FL
15	2		*REAR BUMPER SIDE RETAINER	Serviceable	150.00 FL	*- FL
16	1		*REAR BUMPER REINFORCEMENT	Cracked	465.00 FL	*394.80 FL
17	1		*REAR N/S COLLISION CORNER SENSOR MODEM	Cracked	1,189.00 FL	*1,189.00 FL
18	1		*REAR N/S BUMPER REFLECTOR	Serviceable	95.00 FL	*- FL
19	2		*REAR REVERSE SENSOR	Dented / Shorted	370.00 FL	*370.00 FL
20	1		*REAR REVERSE CAMERA	Serviceable	826.00 FL	*- FL
21	1		*REAR NO PLATE	Dented	40.00 FS	*40.00 FS
22	20		*CLIPS	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,027.00	7,088.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,189.40	1,401.76
Total Parts (\$\$)	8,837.60	5,687.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE / RENEW THE ABOVE PARTS. CUT OUT & REWELD REAR END PANEL, KNOCK OUT & RESHAPE REAR SPARE TYRE PANEL, REAR FENDER, TAIL-LAMP PANEL ETC	New	1,200.00	600.00
2	TO PUTTY & SPRAY PAINT ON REAR ACCIDENT AFFECTED PORTION	New	1,200.00	600.00
3	CHECK / RECONNECT WIRING	New	40.00	20.00
4	REMOVE / REFIT REAR WINDSCREEN	New	120.00	120.00
5	DIAGNOSTIC CHECK AND REMOVE / RENEW REAR COLLISION CORNER SENSOR & RESET SAME	New	280.00	120.00
Gross Labour Cost (S\$)			2,840.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >