

ASS. REC. BY:

REF:

MS6/ CS/MS6 240 90019/Kvp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/INV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: YQ 8616K

Policy No. 30003855029

Claims No. 371861

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 X days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNX 28897

Yr Regn:

01, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante S.c. 1598

Colour

M. Gray

A/C: Insured / Std / NI / NA

Sp. Reading

45797

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM14624157M4111824

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

2/9/24

D.O.I.

3/9/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/ GIA & E&A not in wksp.

10/9/11pm @ 5700h Cuhw (red 5977.60, 51%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

). Extras

). Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Tan Jinng Yi
Blk 190 Canberra Drive
07 - 41
Singapore 767957

Vehicle No : SMX 2889 J
Make : Hyundai Avante
Year :

Fax : 64816131

Not Withheld
11 Lmp @ 5700h
Recovery After Paim
5 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear boot lid ✓
1 pc	Rear windscreen moulding ✓
1 pc	Rear boot lid inner lock ? photo
1 pc	Rear boot lid emblem " Logo ✓
1 pc	Rear boot lid emblem " AVANTE " ✓
1 pc	Rear boot lid top cover ✗
1 pc	Rear boot lid reflector ? photo
2 pcs	Rear tail-lamp assy ✗
1 pc	Rear boot rubber ? photo
1 pc	Rear end panel ? photo
1 pc	Rear end panel inner garnish
1 pc	Rear n/s fender inner trim board reuse
1 pc	Rear bumper ✓
1 pc	Rear bumper lower garnish ✓ 341
2 pcs	Rear bumper side retainer ✓
1 pc	Rear bumper reinforcement ? photo 394.80
1 pc	Rear n/s collision corner sensor modem ? photo
1 pc	Rear n/s bumper reflector ? photo
2 pcs	Rear reverse sensor photo
1 pc	Rear reverse camera reuse

Bu	\$2,073.00	✓
re	\$115.00	✓
nd	\$185.00	✓
re	\$65.00	✓
re	\$75.00	✓
su	\$499.00	✗
cm	\$1,052.00	✓
su	\$875.00	✓
nd	\$1,750.00	✗
nd	\$165.00	✓
Bu	\$485.00	✓
su	\$184.00	✗
su	\$311.00	✗
Bu	\$499.00	✓
nd	\$394.00	✓
\$75.00	\$150.00	✗
cm	\$465.00	✓
cm	\$1,189.00	✓
su	\$95.00	✗
nd	\$370.00	✓
nd	\$826.00	✗
	\$10,947.00	
Less 20 %	\$2,189.40	
	\$8,757.60	

S. Nett Item

1 pc	Rear no plate
20 pcs	Clips

nd	\$40.00	✓
re	\$40.00	✓

Labour Charges

Remove/renew the above parts. Cut out & reweld rear end panel, knock out & reshape

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

rear spare tyre panel, rear fender, tail-lamp panel etc.

\$1,200.00 600l

To putty & spray paint on rear accident affected portion.

\$1,200.00 600l

Check/reconnect wiring.

\$40.00 200

Remove/refit rear windscreen

\$120.00 ✓

Diagnostic check and remove/renew rear collision corner sensor & reset same

\$280.00 1200

Total \$11,677.60