

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLS 5205B

REPLACEMENT OF PARTS						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	FRONT BUMPER	DEFORMED	\$880.00	\$880.00		
1	FRONT BUMPER SIDE RETAINER (LHS)	NOT NECESSARY	\$95.00	\$0.00		
10	FRONT BUMPER CLIPS @\$4.00	NECESSARY	\$40.00	\$40.00		
1	FRONT FENDER (LHS)	BENT	\$498.00	\$498.00		
1	FRONT WHEEL HUP CAP (LHS)	CUT	\$200.00	\$200.00		
1	FRONT RIM (LHS)	TO REPAIR SEE LABOUR	\$500.00	\$0.00		
	LESS 20.00% DISCOUNT		(\$442.60)	(\$323.60)		
			\$1,770.40	\$1,294.40		

Labour				
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
TO REMOVE & REPLACE LHS FRONT RIM & CONDUCT WHEEL BALANCING		\$120.00	\$50.00	
TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT FOR THE REPLACED PARTS		\$100.00	\$40.00	
TO KNOCKING & PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT RIM (LHS)		\$600.00	\$400.00	
TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS		\$600.00	\$400.00	
		\$1,420.00	\$890.00	
GRAND TOTAL		\$3,190.40	\$2,184.40	
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,750.00	
Report Ref No: CS/AWA24090023/Rqp3e2				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.