



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SJR 7537J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRT BUMPER	BUCKLED/DENTED	\$1,917.80	\$960.00
1	FRT BUMPER SIDE RETAINER LH	SERVICEABLE	\$164.80	\$0.00
1	HEADLAMP LH	MTG CRACKED	\$1,917.80	\$1,917.80
	<b>LESS 25.00% DISCOUNT</b>		(\$1,000.10)	(\$719.45)
			\$3,000.30	\$2,158.35
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRT BUMPER CLIPS (SN)	Necessary	\$50.00	\$50.00
			\$50.00	\$50.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS		\$80.00	\$20.00
	TO REMOVE, REPAIR & REPLACE DAMAGED BODYPARTS, REALIGN BODYWORK AND WHERE CONSISTENT TO THE ACCIDENT		\$400.00	\$200.00
	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS		\$400.00	\$220.00
	RUST PROOFING ON AFFECTED PORTIONS	NOT NECESSARY	\$80.00	\$0.00
			\$960.00	\$440.00
<b>GRAND TOTAL</b>			<b>\$4,010.30</b>	<b>\$2,648.35</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>\$2,050.00</b>
Report Ref No: CS/SMO24090024/Kqp3e2				

**KSC**

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repossibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.