

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		7	onale Des Experts En	
	SOMPO INSURANCE SINGAPORE PL		Ref:	CS/SMO24090024/Kqp3e2
	O RAFFLES PLAC	PLACE #03-03 LAND TOWER SINGAPORE 048623	Date:	11/09/2024
J	MINOAI OILE EAINE	TOWER ONIOAI ONE 040020	Code:	SMO
1.		Policy Particulars	:- THIRD PARTY CLA	IM
Ir	nsured Veh.	SLJ 1188R	Veh. Inspected	SJR 7537J
Р	olicy No.	D23MTPV01013123	Coverage	0
С	laim No.	CMTD2402719/SYH	Excess	\$0.00
Α	ssign From	HWANG SHIANG YI	Assign Date	02/09/2024
2.		Vehic	cle Details	
M	lake & Model	TOYOTA ESTIMA (A)	C.C	2362
Е	ingine No.	2AZC017137	Year of Reg.	17/04/2009
С	hassis No.	ACR507004060	Colour	METALLIC DARK BLUE
О)dometer	220117 KM	Steering	IN ORDER
В	Brakes	IN ORDER	General	GOOD
M	lodification(s)	RIMS: SPORTS RIM		
3.		Conditi	ons of Tyres	
		Size	Make	Balance (mm)
R	R/H Front Tyre	225/45ZR18	MICHELIN	5
L	/H Front Tyre	225/45ZR18	MICHELIN	5
R	R/H Rear Tyre	225/45ZR18	MICHELIN	5
L	/H Rear Tyre	225/45ZR18	MICHELIN	5
4.		Description	on of Damages	
THE V	EHICLE SUSTAIN	ED DAMAGES AT THE N/S FRONT	PORTION.	
DAMA	GES SEE DETAIL	S.		
5.		Genera	Information	
Α	ccident Date	20/08/2024	Inspection Date	03/09/2024
S	Survey held at EM SOLUTION PTE LTD - 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITS SINGAPORE 575722			
5a.		Re	emarks	
	· · · · · · · · · · · · · · · · · · ·		DE IIIDIOE! DAOIO	
		AS CONDUCTED ON A"WITHOUT F) YOUR INSTRUCTIONS, WE HAVE		REPAIRS

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days