

88/SMO24090024/Kap3

ASS. REC. BY:

REF:

Kenneth

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MY
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$52k
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 02 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 06/28 Person Contacted: _____ Vehicle: IN / OUT

Veh No: STR 7537J Yr Regn: 04, 09
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Toy Estima C.C. 2362
Colour: M.D. Blue A/C: Insured / Std / NI / NA
Sp. Reading: 220117 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ACR 50 7004060
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/45ZR18
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. 20/8/24 D.O.I. 3/9/2024
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
N/S
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
5/9	11pm @ 2050p Calm cRed 7 (960.30, 49%)

Date/Time, File Pass to? ☐ : Prell. Report
1) 10/9 11pm ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: 2
Resurvey No. of Trip: 1

Report Format: TP
Lump Sum / LB.I: (\$ 2050)

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee: _____
Transportation: _____
S + RS. SI _____
Fuel: _____
Others: _____
TOTAL: _____

EM Solution Pte Ltd

160 Sin Ming Drive #03-19, Sin Ming Autocity
Singapore 575722
Tel: 64560226
GST/Reg. No: 201016308K

ESTIMATE

Date : 2nd Sept 2024

Mdm **Tay Kim Wah**
Blk 337 Bukit Batok St 34, #08-02
Singapore 650337

Veh No : **SJR 7537J**
Make/Model : **Toyota Estima**
Chassis No : ACR507004060
Date of Acc : 20.08.24
TP Veh No : SLJ 1188R

*NOT WITHIN
11 Sep @ 2050h
Repair After Rain
2 days*

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Frt Bumper <i>960</i>	<i>Bul/nd</i> \$	1,917.80 ✓
2	1 pc	Frt Bumper Side Retainer LH	\$	164.80 x
3	1 pc	Headlamp LH	<i>my.m</i> \$	1,917.80 ✓
			\$	4,000.40
			Less 25%	\$ 1,000.10
				\$ 3,000.30
4	1 set	Frt Bumper Clips	S/Nett	\$ 50.00
			Parts Total :	\$ 3,050.30
Labour				
1		To remove & rearrange electrical wirings, check lightings	\$	80.00 <i>2d</i>
2		To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.	\$	400.00 <i>20d</i>
3		Putty and respray painting on affected portions.	\$	400.00 <i>22d</i>
4		Rust proofing on affected portions.	\$ <i>nn</i>	80.00 x
			Labour Total :	\$ 960.00
			Total Parts & Labour :	\$ 4,010.30

for E M Solution Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: