

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III24090025/UDP3E2

Date: 10/09/2024

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	SCJ2808K	Insured Vehicle No :	SMZ5431R
Date of Loss:	30/08/2024	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCJ2808K	Engine No:	27195631195827
Make & Model:	MERCEDES-BENZ E200K, 1.8 (A)	Chassis No:	WDB2110412B439125
Reg. Date:	25/06/2009 (Man. Year: 2009)	Odometer:	270225 km
Colour:	Blue		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	265/35 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,209.12	10,861.87	13,347.25	55.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,030.00	1,790.00	3,240.00	64.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,239.12	12,651.87	16,587.25	56.73
Approved Total (Overridden) (S\$)		10,000.00		
Nett Amount (S\$)	29,239.12	10,000.00	19,239.12	65.80

INSPECTION

Date of Assignment:	02/09/2024	We Garage (HQ)
Date Inspected:	03/09/2024	Inspected At: 1 Kaki Bukit Avenue 6, #02-11 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2024)
Parts:	143	MERCEDES-BENZ E200K 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCJ2808K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP - LH	Not Necessary	2,695.00 FL	*- FL
2	1		*FRONT BUMPER	Cut / Torn	2,198.00 FL	*1,755.21 FL
3	1		*FRONT BUMPER FOG LAMP	Not Necessary	325.00 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER	Not Necessary	185.00 FL	*- FL
5	1		*FRONT BUMPER INNER SPONGE	Not Necessary	165.00 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	596.00 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER	Cracked	75.00 FL	*75.00 FL
8	1		*FRONT BUMPER CHROME MOULDING	Necessary	125.00 FL	*125.00 FL
9	2		*FRONT BUMPER SIDE PDC SENSORS	Not Necessary	710.00 FL	*- FL
10	1		*FRONT BUMPER SIDE UNDERCOVER	Not Necessary	355.00 FL	*- FL
11	1		*FRONT FENDER - LH	Distorted	1,550.00 FL	*1,212.35 FL
12	1		*FRONT FENDER INNER SHIELD	Torn	175.00 FL	*175.00 FL
13	1		*FRONT FENDER SIDE PROTECTOR	Broken	85.00 FL	*85.00 FL
14	1		*FRONT WHEEL RIM - LH	Warped / Bent	2,880.00 FN	*600.00 F
15	1		*FRONT WHEEL HUB WITH BEARING	Damaged	587.54 FL	*587.54 FL
16	1		*FRONT SHOCK ABSORBER	Serviceable	727.78 FL	*- FL
17	1		*FRONT KNUCKLE ARM	Bent	1,027.09 FL	*1,027.09 FL
18	1		*FRONT LOWER ARM	Twisted	1,038.00 FL	*1,038.00 FL
19	1		*FRONT TOP ARM	Not Necessary	479.20 FL	*- FL
20	1		*FRONT CONTROL ARM	Not Necessary	437.00 FL	*- FL
21	1		*STABILIZER BAR LINK	Not Necessary	97.10 FL	*- FL
22	1		*FRONT DOOR - LH	Twisted / Cracked	3,126.00 FL	*2,980.00 FL
23	1		*FRONT DOOR CHECKER	Twisted	155.00 FL	*155.00 FL
24	2		*FRONT DOOR HINGES	Not Necessary	330.00 FL	*- FL
25	1		*FRONT DOOR INNER BOARD	Not Necessary	1,000.00 FL	*- FL
26	1		*FRONT DOOR LOCK	Not Necessary	435.00 FL	*- FL
27	1		*FRONT DOOR CHROME PROTECTOR	Bent	165.00 FL	*165.00 FL
28	1		*FRONT DOOR SIDE MIRROR	Damaged / Cracked	758.00 FL	*758.00 FL
29	1		*FRONT DOOR WEATHERSTRIP	Necessary	295.00 FL	*295.00 FL
30	1		*ROCKER PANEL	Repair	995.00 FL	*- FL
31	1		*ROCKER PANEL OUTER GARNISH	Cut / Torn	655.00 FL	*655.00 FL
32	1		*FRONT DOOR PROTECTOR	Bent	225.00 FL	*225.00 FL
33	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*40.00 FS
34	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	60.00 FS	*40.00 FS
35	1		*FRONT TYRE	Serviceable	650.00 FS	*- FS
					Sub Total (\$\$)	
					25,441.71	11,993.19
					- List Item Discount on L Items 5.00/10.00% (\$\$)	
					1,088.59	1,131.32
					- Nett Item Discount on N Items 5.00/0.00% (\$\$)	
					144.00	0.00
					Total Parts (\$\$)	
					24,209.12	10,861.87

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	0.00
3	TO REMOVE AND REFIT FRONT SENSOR	New	200.00	30.00
4	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	250.00	150.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
6	TO REMOVE, REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTING	New	200.00	60.00
7	TO APPLY UNDERCOATING	New	200.00	50.00
8	PANEL BEATING	New	2,000.00	500.00
9	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,800.00	900.00
Gross Labour Cost (S\$)			5,030.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >