

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24090026/UPA3Q2**Date:** 13/12/2024**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MFL0001087_06
Claimant Vehicle No : SLX6342E **Insured Vehicle No :** PC6327M
Date of Loss: 29/08/2024 Nature of Claim: TP Claim No: MFL2024D0010333

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX6342E**
Make & Model: HONDA SHUTTLE, 1.5 G CVT (A) Engine No: L15B5460447
Reg. Date: 02/04/2018 (Man. Year: 2018) Chassis No: GK81200381
Colour: Black Odometer: 107155 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	506.88	506.88	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	300.00	110.00	190.00	63.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	806.88	616.88	190.00	23.55
+ GST 9.00/9.00% (S\$)	72.62	55.52	17.10	23.55
Nett Amount (S\$)	879.50	672.40	207.10	23.55
+ Loss of Use (1.0 x S\$60.00/day) (S\$)		60.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		734.58		

INSPECTION

Date of Assignment: 01/10/2024
Date Inspected: 01/10/2024 Inspected At: Progressive Car Care Pte Ltd (HQ)
Singapore 408716
Estimated Period of Repair: 1.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Nov 2024)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX6342E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR ASSY - RH	Cracked	573.30 FL	*573.30 FL
2	1		*SIDE MIRROR OUTER COVER - RH	Broken/ Missing	60.30 FL	*60.30 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					633.60	633.60
- List Item Discount on L Items 20.00/20.00% (S\$)					126.72	126.72
Total Parts (S\$)					506.88	506.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE SIDE MIRROR	New	150.00	60.00
2	TO RESPRAY PAINT ON SIDE MIRROR COVER	New	120.00	50.00
3	TO CHECK WIRING	New	30.00	0.00
Gross Labour Cost (\$\$)			300.00	110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >