



Your Ref : 23/24/24/VC06/029746

Date: 12<sup>th</sup> September 2024

Our Ref : CS/LPC24090028/Jvh3m4

**M/s Lonpac Insurance Bhd**

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE XD 2119Z  
ACCIDENT ON 21/08/2024**

Instruction was received to inspect the vehicle Reg. No. XD 2119Z. The inspection was conducted on 03/09/2024 at the premises of M/s Mah Lian Motor Vehicle Repairer, 38 Defu Lane 9, Singapore 539278.

The following vehicle information was recorded:

Registration Number	: XD 2119Z
Make/Model	: Isuzu CYZ52L
Year of Registration	: 2008
Body Colour	: White
Chassis Number	: JALCYZ52L87000005
Engine Capacity	: 15681 cc
Speedometer Reading	: N/A

The vehicle caught fire. The cause of fire probably due to electrical short circuit. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	48,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$	20,712.00)
Nett Liability	S\$	27,288.00
	=====	

Vehicle Inspected By:



ELTON SEET BOON KIAT  
Asst. Automotive Assessor



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.