



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMB 1559J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	COVER, HEADLAMP:FRT, LH, FOR MAN A22 BUS	CRACKED	\$974.70	\$974.70
1	FLASHER, AUX HEADLAMP, RH (MAN BUS)	CRACKED	\$904.40	\$904.40
1	HEADLAMP, LH (MAN BUS)	CRACKED	\$1,603.60	\$1,603.60
1	RETAINER:MALE & FEMALE, REAR LID, MAN BUS	DISTORTED	\$74.80	\$74.80
1	DOME:FRONT, FOR MAN A22 BUS	TO REPAIR SEE LABOUR	\$2,817.50	\$0.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$355.75)
			\$6,375.00	\$3,201.75

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF DOME:FRONT, FOR MAN A22 BUS		\$1,590.00	\$1,060.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$708.00	\$616.00
			\$2,298.00	\$1,676.00

GRAND TOTAL	\$8,673.00	\$4,877.75
--------------------	-------------------	-------------------

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$4,250.00
---------------------------------------------------------------------------------	--	-------------------

Report Ref No: CS/GAI24090035/Tvp3e2

MTH

MOHAMAD TAUFIKH

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.