

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24090039/RQH3E2
Date: 17/12/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SMH2996S **Insured Vehicle No :** GBF3267Y

Date of Loss: 26/08/2024 Nature of Claim: TP Claim No: DMCV2400171H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH2996S**

Make & Model: MAZDA 6, 2.0 V SDN (GH) (A) Engine No: PE21248620

Reg. Date: 17/01/2019 (Man. Year: 2018) Chassis No: JM6GL1072K0310963

Colour: Red Odometer: 51104 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,049.39	1,491.67	557.72	27.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,354.00	2,317.00	2,037.00	46.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,403.39	3,808.67	2,594.72	40.52
+ GST 9.00/9.00% (S\$)	576.31	342.78	233.53	40.52
Nett Amount (S\$)	6,979.70	4,151.45	2,828.25	40.52

INSPECTION

Date of Assignment: 02/09/2024

Date Inspected: 05/09/2024 Inspected At: Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ)
27A Tanjong Penjuru
Singapore 609042

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2024)
Parts:	143	MAZDA 6 2.0 V SDN (GH) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH2996S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*REAR BUMPER W/PK SENSOR GL	Deformed	1,260.75 FS	*1,260.75 FS
3	4		*GROMMET, SCREW	Necessary	9.44 FS	*9.44 FS
4	4		*NUT, CLIP	Necessary	9.44 FS	*9.44 FS
5	2		*RUBBER, SEAL GL	Necessary	27.82 FS	*27.82 FS
6	6		*FASTENER	Necessary	14.16 FS	*14.16 FS
7	2		*RIVET	Necessary	14.84 FS	*14.84 FS
8	4		*TAPE, PROTECTOR	Necessary	29.68 FS	*29.68 FS
9	1		*BRACKET, BUMPER SKYACTIV	Not Necessary	4.64 FS	*- FS
10	1		*REINF REAR BUMPER GJ/GL	Not Necessary	523.08 FS	*- FS
11	1		*GASKET (R), RR.COMB. GL3	Necessary	52.77 FS	*52.77 FS
12	1		*GASKET (L), RR.COMB. GL3	Necessary	52.77 F	*52.77 F
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					2,049.39	1,491.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE REAR BUMPER AND ALL ACCIDENT AFFECTED AREA	New	1,584.00	792.00
2	TO RESPRAY REAR BUMPER	New	1,890.00	945.00
3	TO TRANSFER REVERSE SENSORS	New	330.00	180.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	300.00	250.00
Gross Labour Cost (\$\$)			4,354.00	2,317.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >