

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/III24060140/KMA3Q2**Date:** 13/01/2026**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MFL0000767  
**Claimant Vehicle No :** SHC5135B **Insured Vehicle No :** SMJ4084A  
 Date of Loss: 15/06/2024 Nature of Claim: TP Claim No: MFL2024D0007422

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SHC5135B**  
 Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2H02481  
 Reg. Date: 15/10/2020 (Man. Year: 2020) Chassis No: JTDKB3FU203092239  
 Colour: Metallic Pearl White/Red Odometer: 354273 km  
 Engine Capacity: 1798 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: Wanli 9 mm Rear Left Side: Wanli 3 mm  
 Front Right Side: Wanli 9 mm Rear Right Side: Wanli 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,404.03	3,141.25	4,262.78	57.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,990.00	1,060.00	3,930.00	78.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,394.03</b>	<b>4,201.25</b>	<b>8,192.78</b>	<b>66.10</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,150.00</b>		
<b>(S\$)</b>	12,394.03	3,150.00	9,244.03	74.58
<b>+ GST 9.00/9.00% (S\$)</b>	1,115.46	283.50	831.96	74.58
<b>Nett Amount (S\$)</b>	<b>13,509.49</b>	<b>3,433.50</b>	<b>10,075.99</b>	<b>74.58</b>
<b>+ Car Rental (4.0 x S\$82.84/day) (S\$)</b>		331.36		
<b>+ Loss of Earnings (4.0 x S\$40.00/day) (S\$)</b>		160.00		
<b>+ Doc/Search Fee (S\$)</b>		27.25		
<b>Nett Liability (S\$)</b>		<b>3,952.11</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,950.00</b>		

**INSPECTION**

Date of Assignment: 19/06/2024  
 Date Inspected: 19/06/2024 Inspected At: Trans-cab Auto Services Pte Ltd  
 No 2 Ang Mo Kio Street 63  
 Singapore 569111  
 Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

We have checked and confirmed that all part prices are correct. The actual work carried out and listed as labour and spray painting is accurate, and the fees charged for labour and spray painting are correct.

# REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2024)
<b>Parts:</b> 144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHC5135B)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FRONT BUMPER	Buckled / Cut	653.31 FL	*653.31 FL
2	1		*ABSORBER,FRONT BUMPER ENERGY	Serviceable	100.91 FL	*- FL
3	1		*REINFORCEMENT SUB-ASSY ,FRONT BUMPER	Repair	902.16 FL	*- FL
4	1		*SUPPORT ,FRONT BUMPER SIDE, RH	Serviceable	100.49 FL	*- FL
5	1		*MOULDING FRONT BUMPER SIDE RH	Serviceable	120.86 FL	*- FL
6	1		*GRILLE SUB-ASSY ,RADIATOR	Serviceable	532.88 FL	*- FL
7	1		*GRILLE ,RADIATOR ,LOWER NO .1	Serviceable	224.70 FL	*- FL
8	1		*JAR ASSY ,WINDSHIELD WASHER	Serviceable	276.15 FL	*- FL
9	1		*FENDER SUB-ASSY ,FRONT RH	Buckled	1,236.69 FL	*1,236.69 FL
10	1		*LINER ,FRONT FENDER RH	Distorted	255.36 FL	*255.36 FL
11	1		*EMBLEM ,SIDE PANEL RH	Necessary	68.88 FL	*68.88 FL
12	1		*UNIT ASSY ,HEADLAMP RH	Serviceable	3,325.56 FL	*- FL
13	1		*MIRROR ASSY ,OUTER REAR VIEW RH	Dented / Jammed	1,814.09 FL	*1,814.09 FL
14	1		*FRT BUMPER CLIP	Necessary	65.00 FS	*60.00 FS
15	1		*FENDER LINER CLIP	Necessary	65.00 FS	*60.00 FS
16	1		*FRT BUMPER SIDE RETAINR CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>9,807.04</b>	<b>4,148.33</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	2,403.01	1,007.08
<b>Total Parts (\$)</b>	<b>7,404.03</b>	<b>3,141.25</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RUST -PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	30.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	500.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	2,000.00	450.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
7	TO TRANSFER OF REAR FENDER PANEL FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
			<b>Gross Labour Cost (\$)</b>	<b>4,990.00</b>
				<b>1,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >