

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24090042/KQP3M4  
Date: 30/10/2024

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SNK1927X	Insured Vehicle No :	SJH1752X
Date of Loss:	28/08/2024	Nature of Claim:	TP
		Claim No:	DMPC2401136H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNK1927X		
Make & Model:	NISSAN SERENA, 1.2 L HIGHWAY STAR PREMIUM E-POWER (A)	Engine No:	HR12227635L
Reg. Date:	27/03/2023 (Man. Year: 2023)	Chassis No:	JN1EBAC27Z0001749
Colour:	Metallic Grey	Odometer:	96172 km
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R16	Rear Tyre Size:	195/60R16
Front Left Side:	Davanti 8 mm	Rear Left Side:	Davanti 8 mm
Front Right Side:	Davanti 8 mm	Rear Right Side:	Davanti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,301.60	3,562.60	1,739.00	32.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,370.00	630.00	31.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,301.60	4,932.60	2,369.00	32.44
+ GST 9.00/9.00% (S\$)	657.14	443.93	213.21	32.45
Nett Amount (S\$)	7,958.74	5,376.53	2,582.21	32.44

INSPECTION

Date of Assignment:	03/09/2024		
Date Inspected:	03/09/2024	Inspected At:	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD SINGAPORE 579701
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG      Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2024)
Parts:	M1-MPV	NISSAN SERENA 1.2 L HIGHWAY STAR PREMIUM E-POWER (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNK1927X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,575.00 FL	*1,575.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
3	1		*RHR BUMPER RETAINER	Serviceable	45.00 FL	*- FL
4	1		*LHR BUMPER RETAINER	Distorted	45.00 FL	*45.00 FL
5	1		*REAR TAILGATE	Bent	1,939.00 FL	*1,939.00 FL
6	1		*TAILGATE WEATHERSTRIP	Dented	120.00 FL	*120.00 FL
7	1		*EMBLEM HIGHWAY STAR	Necessary	75.00 FL	*75.00 FL
8	1		*EMBLEM E-POWER	Necessary	105.00 FL	*105.00 FL
9	1		*EMBLEM NISSAN	Not Necessary	95.00 FL	*- FL
10	1		*REAR W /S MLDG	Not Necessary	120.00 FL	*- FL
11	4		*REVERSE SENSOR	Serviceable	960.00 FL	*- FL
12	1		*SENSOR BRACKET	Serviceable	640.00 FL	*- FL
13	1		*INNER SEAL	Not Necessary	30.00 FS	*- FS
14	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
15	1		*REAR NO.PLATE	Serviceable	35.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	5,879.00 3,954.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	577.40 391.40
					Total Parts (\$\$)	5,301.60 3,562.60

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA, TO REMOVE & REFIT DAMAGE PARTS	New	750.00	600.00
2	TO PUTTY,RESPRAY ON REAR BUMPER,REAR TAILGATE REAR END PANEL,AFFECTED AREA	New	1,000.00	600.00
3	TO REMOVE/REFIT REAR WINDSCREEN	New	120.00	120.00
4	TO TUFF COAT ON WELD AREA	New	80.00	30.00
5	TO CHECK WIRING, REFIT REVERSE SENSOR, TAILLAMP	New	50.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,000.00</b>	<b>1,370.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >