SNK1927X



Our Ref:

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Vehicle No.

pe of Claim :	TP(ECICS)	Make & Model	NISSAN SERENA
pe of Claim		Year of Manufacture	2023
		Chassis No.	JN1EBAC27Z0001749
			HR12227635L
s Company :	III	Engine No.	:
xcess :		Policy No. Time of Accident	
ate of Accident :	28/8/2024		occor.
suggested Days of Repair	r:	In-house Vehicle Asse	
		Case Owner	KELVIN
Repair Estimates		Signature	:
Parts (a) Cost / List Price	e Items \$ 5,774.00		
Plus/Less	E 77 40		
Total of Cost	F 406 60	Operation KELVIN SU	
		TEL: 9786 423	6
(b) Nett Price Iten	ms	E: kelvinsukwe	en@cdge.com.sg
Less		SUN PIN	16
Total of Nett I	Item	TEL: 9728 891 E: oisunpin@c	edge com so
	405.00		Not Notha Reamy 134p
(c) Special Nett I	items		Reave Blo
Total Parts Cost (App	endix A) \$ 5,301.60	•	The first
Labour (Appendix B)	£ 2,000,00	-	Q 4932. Ko
Total Repair Cost	\$ 7,301.60	-	@ (1)p.00
	e subjected to 9% G.S.T.		
The above total will be	· → Jano J SUP	Kenn	adh
Name of Surveyor	: <u></u>	Kenne	701
	:	2/0/21	
Company Survey conducted	l on :	<i>3/9/24</i> at	
Survey conductor			
1			
Remarks By Surv	reyor	30 509	-tion
Remarks By Surv	r <u>eyor</u> this vehicle is aut nor ized / is r	not authorized until further	notice.
(a) The repair of t	this vehicle is authorized / is need Days of Repair		notice.
(a) The repair of t	this vehicle is authorized / is need Days of Repair	not authorized until further of the day (s) and frequired	notice.
(a) The repair of t	this vehicle is authorized / is red Days of Repair :		notice.
(a) The repair of t	this vehicle is authorized / is need Days of Repair		notice. 3/9/29

VACCIDENT REPAIR ESTIMATES/F3

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Spare Parts		Case Owner:	KELVIN
Vehicle No	: SNK1927X		
	NISSAN SERENA	Year Manufacture:	2023
Make & Model		Engine No:	HR12227635L
Chassis No	: JN1EBAC27Z0001749		
		Supplier:	
Sales Order	-	Type of Claim:	TP(ECICS)
	· KELVIN	- Type of Oldini	•

der	By : KELVIN DESCRIPTION	QTY	Cost Price		List Price	Ş	5/N	Disposition By Surveyor
No	DESCRIPTION	-	By	\$	1,575.00			
1 0	REAR BUMPER	1	New	\$	55.00			
2 5	REAR BUMPER CLIPS	10	In	\$	45.00			X
2 5	RHR BUMPER RETAINER	1	011	+	.= 00			
3 1	THE PLUMPED DETAINER	1	R	\$				
4 1	REAR TAILGATE 1939	1	RU	+ +				
5	TAILGATE WEATHERSTRIP	1	New	\$				
6	EMBLEM"HIGHWAY STAR"	1	Ne					
/	EMBLEM"E-POWER"	1	NA	_				×
8	EMBLEM L-1 GTT L-1 EMBLEM NISSAN"	1	The state of the s	+	120.00			×
9	REAR W/S MLDG	1	NA	-	\$ 960.0			X
10	REVERSE SENSOR	4	Su	-	\$ 640.0			X
11	SENSOR BRACKET	1	12	+	\$ 040.0	\$	30.0	00
12	SENSOR BRACKE	1		+	Na	-	F	00
	INNER SEAL	1		+	Su			
14	4 SEALANT	1		\dashv	10	+		
_	REAR NO.PLATE			-		+		
1				\dashv		+		
1				-	Marie Control of the	416.4		
1	8		LKK Auto Cons	sulta	nts hence no	ottry		
1	9		the Repairer o	tine	er soray painth	19		
	20		and the second of the second of	2000	nanisi ilili			
2	21		To display dame Parts prices are Third party sun	subj	ect to confirmat	rejudice	basis	
1	22							
	23		- No filegal modi	v item	n(s) must be res	urveyed	ompany	
	24		is subject to fir	nal ap	proval from Ins	arance c		
	25		Acknowledged	by Re	epairer			
	26		Signature:					
	27		Date:		Anna de la constitución de la co			
	28		A.E.					3 32
	29							1
-	30 Star mustod parts are recomm	1 11	he renaired th	en a	an addition	al lab	our cha	rge

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax: 62815767

Labour					KELVIN
Vehicle No.	: _	SNK1927X	Case Owner Year of Manufacture	:	2023
Make & Model	: _	NISSAN SERENA	real of Manager	Esimated	Adjusted

lake	NISSAN SERENA Year of Manufacture Labour Description	Esimated Price		Adjusted Price
/No		\$	750.00	600/
,	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA, TO REMOVE &	-		
1	REFIT DAMAGE PARTS	_		
		0	1,000.00	6006
	TO PUTTY, RESPRAY ON REAR BUMPER, REAR TAILGATE	Φ	1,000.00	
2	REAR END PANEL, AFFECTED AREA	_		
	REAR END PANEL, ALT ESTED		100.00	
	DEAD WINDSCREEN	\$	120.00	
3	TO REMOVE/REFIT REAR WINDSCREEN			301
	T. D. ADEA	\$	80.00	301
4	TO TUFF COAT ON WELD AREA			2-1
	TALLAMP	\$	50.00	201
5	TO CHECK WIRING, REFIT REVERSE SENSOR, TAILLAMP			
_				
-				
\vdash		_		
-		_		
-				
		_		
				-
-				
H				
-				
-				
L				-
+				
+				
1				
-				

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.