



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: FIONA SHEN

Ref: CS/INC24090044/Anh3e2(N)

Date: 25/04/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLD 9748D	Veh. Inspected	SLD 8033P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1293142-002	Excess (\$)	0.00
Assign From	FIONA SHEN	Assign Date	03/09/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VELLFIRE	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTNGF3DH308003860	Colour	BLACK
Odometer	416567 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R18	KAPSEN	6 mm
L/H Front Tyre	235/55 R18	KAPSEN	6 mm
R/H Rear Tyre	235/55 R18	KAPSEN	6 mm
L/H Rear Tyre	235/55 R18	KAPSEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/08/2024	Inspect Date / Time	04/09/2024 (01:34 PM)
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
--	------------------------