



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBK 268M

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	CUT	\$1,500.00	\$1,150.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	\$500.00	\$0.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	\$600.00	\$0.00
1	FRONT BUMPER RH FOGLAMP	NOT NECESSARY	\$300.00	\$0.00
1	FRONT BUMPER RH FOGLAMP GARNISH	CUT	\$250.00	\$250.00
1	FRONT BUMPER RH SIDE RETAINER	NOT NECESSARY	\$150.00	\$0.00
1	FRONT BUMPER SPONGE	NOT NECESSARY	\$200.00	\$0.00
1	FRONT BUMPER TOW HOOK COVER	NOT NECESSARY	\$150.00	\$0.00
1	FRONT GRILLE	NOT NECESSARY	\$750.00	\$0.00
1	FRONT GRILLE OUTER COVER	NOT NECESSARY	\$750.00	\$0.00
1	FRONT RH FENDER	DISTORTED	\$550.00	\$550.00
1	FRONT RH FENDER INNER SHIELD COVER	TORN	\$250.00	\$250.00
1	FRONT RH HEADLAMP	CRACKED	\$715.00	\$715.00
1	FRONT RH KNUCKLE ARM	DAMAGED	\$512.00	\$512.00
1	FRONT RH KNUCKLE ARM BEARING	DAMAGED	\$195.00	\$195.00
1	FRONT RH LOWER RM	BENT	\$339.00	\$339.00
1	FRONT RH SHOCK ABSORBER	NOT NECESSARY	\$494.00	\$0.00
1	FRONT RH TIE ROD END	NOT NECESSARY	\$207.00	\$0.00
	LESS 10.00% DISCOUNT		(\$841.20)	(\$396.10)
			\$7,570.80	\$3,564.90
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT RH SPORT RIM (SN)	CUT	\$625.50	\$400.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	\$25.00	\$25.00
1	SET FRONT GRILLE CLIPS (SN)	NOT NECESSARY	\$30.00	\$0.00
1	SET FRONT RH INNER SHIELD COVER CLIPS (SN)	NECESSARY	\$30.00	\$30.00
1	FRONT RH TYRE (SN)	NOT NECESSARY	\$280.00	\$0.00
			\$990.50	\$455.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING. (TO FR)		\$80.00	\$30.00
	TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC		\$240.00	\$180.00
	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM		\$100.00	\$80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$500.00	\$200.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT		\$600.00	\$400.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	NOT NECESSARY	\$80.00	\$0.00
			\$1,600.00	\$890.00
GRAND TOTAL			\$10,161.30	\$4,909.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$3,900.00
Report Ref No: CS/INC24060141/Avh3				

TOTAL FOR SPARE PARTS: \$ 8,561.30 \$ 4,019.90
TOTAL FOR LABOUR : \$ 1,600.00 \$ 890.00
TOTAL REPAIR COST: \$10,161.30 \$ 4,909.90

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.