

ASS. REC. BY:

REF: TH 1Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of 176 04 Weja 733J

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 836K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 4-5 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN9039PYr Regn: 05.17Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or (A)Make: Mazda 3c.c. 1496Colour: M. Silver

AC: Insured / Std / NI / NA

Sp. Reading: 175741

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BN22A.8H0150394Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Triangle

Front

Rear

R/Bal. 5 mmR/Bal. 6 mmL/Bal. 5 mmL/Bal. 6 mmD.O.A. 14/8/24D.O.I. 2/9/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transport: _____

Add Fee: ☐

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

S + RS. \$ _____

: Extras _____

: Others _____

Report Format: _____

mp Sum / I.B.I: (\$ _____)



WEGA ENGINEERING

automotive workshop and beyond

Blk 176, Sin Ming Drive, #04-16, Sin Ming Autocare, Singapore 575721
TEL : 65-6452 149 FAX : 65-6452 9153 GST REG NO : 1999 00741 Z

TO : **India International Insurance Pte Ltd**

6 Raffles Quay

#22-00,

Singapore 048580

Date of Accidents: 14/08/2024

EMAIL : motorclaim@iii.com.sg

ATTN : **MOTOR CLAIMS DEPT**

VEHICLE ESTIMATE : **TP 08/4584**

DATE : **16-Aug-24**

VEHICLE NO : **SLN9039P**

MODEL : **Mazda 3**

REG YEAR : **2017**

CHASSIS NO : **JM6BN22A8H0150394**

Part Cost					
S/N	DESCRIPTION		Qty	Unit Price \$	AMOUNT \$
1	FRONT BUMPER	Bu	1	\$994.32	\$994.32
2	BUMPER RETAINER, RH	Sm	1	\$15.77	\$15.77
3	BUMPER RETAINER, LH	Sm	1	\$15.77	\$15.77
4	BUMPER SPONGE		1	\$38.10	\$38.10
5	FRONT BUMPER REINFORCEMENT		1	\$576.77	\$576.77
6	FRONT BUMPER GRILE, UPPER	CM	1	\$163.43	\$163.43
7	FRONT BUMPER GRILE, LOWER		1	\$163.43	\$163.43
8	FRONT BUMPER GRILE CLIP	Mc	10	\$5.00	\$50.00
9	FRONT TOW COVER, RH	Sm	1	\$39.62	\$39.62
10	FRONT TOW COVER, LH	Sm	1	\$39.62	\$39.62
11	FRONT RADIATOR MOULDING GRILE, RH	CM	1	\$273.53	\$273.53
12	FRONT RADIATOR MOULDING GRILE, LH	CM	1	\$273.53	\$273.53
13	HEADLAMP, RH		1	\$1,228.05	\$1,228.05
14	HEADLAMP, LH		1	\$1,228.05	\$1,228.05
15	HEADLAMP BRACKET, RH	Mc	1	\$473.00	\$473.00
16	HEADLAMP BRACKET, LH	Mc	1	\$473.00	\$473.00
17	FOG LAMP, RH	Sm	1	\$185.52	\$185.52
18	FOG LAMP, LH	Sm	1	\$185.52	\$185.52
19	FOG LAMP COVER, RH	Sm	1	\$31.53	\$31.53
20	FOG LAMP COVER, LH	Sm	1	\$31.53	\$31.53
21	LOGO EMBLEM	Mc	1	\$74.18	\$74.18
22	FRONT BONNET	Mc	1	\$1,147.47	\$1,147.47
23	FRONT BONNET HINGE, RH	Mc	1	\$45.01	\$45.01
24	FRONT BONNET HINGE, LH	Mc	1	\$45.01	\$45.01
25	FRONT SUPPORT PANEL		1	\$479.34	\$479.34
26	TOP PANEL	Mc	1	\$576.77	\$576.77
27	CONDENSER		1	\$1,085.18	\$1,085.18
28	RADIATOR	Sm	1	\$1,144.94	\$1,144.94
29	NUMBER PLATE WITH CASING	Mc	1	\$84.04	\$84.04
Total Part Cost :					\$11,162.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorize
Lump &
Return After Paint
4-5 days


Labour Cost				
S/N	DESCRIPTION	Qty	Unit Price \$	AMOUNT \$
1	TO CHECK AND REPAIR HEADLAMP & FOG LAMP WIRING	1	\$250.00	\$250.00
2	TO REPAIR PANEL BEATING & DISMANTLE AND REPLACE FRONT BUMPER, FRONT BONNET, SUPPORT PANEL & TOP PANEL	1	\$500.00	\$500.00
3	TO PUTTY & SPRAY PAINTING FRONT BUMPER, FRONT BONNET, SUPPORT PANEL & TOP PANEL	1	\$2,000.00	\$2,000.00
4	TO REMOVE AND REFIT CONDENSER & RADIATOR	1	\$800.00	\$800.00
5	TO VACCUM AND TOP UP AIRCON GAS	1	\$200.00	\$200.00
6	TO APPLY RUST PROOFING, VACUUM INTERIOR AND WASH CAR	1	\$200.00	\$200.00
Total Labour Cost :				\$3,750.00

201
7
5001
7
7
X

Amount :	\$14,912.03
GST (9%) :	\$1,342.08
Grand Total :	\$16,254.11

ALL PRICES QUOTED ARE IN SINGAPORE DOLLAR AND SUBJECT TO 9% GST

Estimate prepared and authorised by:



Jeremy Goh

Executive

Wega Engineering Pte Ltd

Date: 16/08/2024

SA1B248FM002 / AH LIM MOTOR COMPANY (BRANCH)
ENTRY DATE & TIME: 15/08/2024 12:09 (SGT)
SUBMITTED BY: GERALD CHEW
VERSION: 1 (15/08/2024 12:09 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	15/08/2024 12:09 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	14/08/2024 18:11 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	JURONG GATEWAY ROAD, OPEN SPACE CAR PARK OF JURONG PLAY GROUND
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN9039P
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN WEI JIAN
NRIC No	SXXXX733J
Email Address	KIRATAN90@GMAIL.COM
Mobile Phone No	(Phone) +65-82827685
Alternative Phone No	-

VEHICLE PARTICULARS


Manufacturer	Mazda
Model	MAZDA3 SEDAN 1.5 AT EU6
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496
Vehicle Fuel	Petrol
First Registration Date	22/05/2017
Chassis no	JM6BN22A8H0150394
Effective Date/Time of Ownership	18/06/2018 10:06 (SGT)

INSURANCE COMPANY

Name of Insurance Company	FWD Singapore Pte. Ltd.
Policy Number / Cover Note Number	PNPV2020-00004819-04

DRIVER

SUPPLEMENT



15/08/2024





SINGAPORE
POLICE FORCE



T/20240814/7120

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

3 of 4

Report No. T/20240814/7120

CONTINUATION OF REPORT

instead.

I wish to state that I had already downloaded my in-car camera footages. However, I could not upload into EPC system due to large file size. I had already informed my insurance company about this matter as well. I will send my car to workshop for further assessment on the next day as well. That's all.