



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2401456
INV Date : 20-11-2024

Reference CD/FCI24090057/Dma3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SKQ 69H
Insured Veh. SHA 1216M
Claim No. D24007652MFCT/CTPL/TPD 2
Policy No. D-24101861MFCT
Accident Date 29/08/2024
Inspection Date 04/09/2024

Description	Amount
Third Party Express Settlement	450.00
Sub-Total	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CD/FCI24090057/Dma3q2
16 RAFFLES QUAY	Date:	20/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SHA 1216M	Veh. Inspected	SKQ 69H
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24007652MFCT/CTPL/TPD 2	Excess	\$0.00
Assign From	KAREN TAN	Assign Date	27/08/2024

2. Vehicle Details

Make & Model	TOYOTA ALPHARD 2.5S CVT	C.C	2493
Engine No.	2AR1274111	Year of Reg.	23/10/2015
Chassis No.	AGH300012726	Colour	WHITE
Odometer	224808 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/50R18	YOKOHAMA	5
L/H Front Tyre	235/50R18	YOKOHAMA	5
R/H Rear Tyre	235/50R18	YOKOHAMA	5
L/H Rear Tyre	235/50R18	YOKOHAMA	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/08/2024	Inspection Date	04/09/2024
Survey held at	ALFRED AUTO SERVICES & SUPPLIES BLK 5035 ANG MO KIO 3 #01-355 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569538		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKQ 69H

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	BROKEN /CUT	\$1,990.00	\$1,185.00
1	FRONT BUMPER RETAINER	BROKEN	\$238.00	\$141.00
1	FRONT BUMPER FOG LAMP	NOT NECESSARY	\$499.80	\$0.00
1	FRONT BUMPER FOG LAMP CHROME	NOT NECESSARY	\$239.60	\$0.00
1	FRONT BUMPER FOG LAMP GRILLE	NOT NECESSARY	\$208.50	\$0.00
1	FRONT RH FENDER	TO REPAIR SEE LABOUR	\$910.60	\$0.00
1	FRONT RH FENDER DUST GARNISH	NOT NECESSARY	\$240.80	\$0.00
10	FRONT RH FENDER DUST GARNISH CLIPS @\$6.00	NOT NECESSARY	\$60.00	\$0.00
2	FRONT RH FENDER DUST HOLD CLIPS @\$15.00	NOT NECESSARY	\$30.00	\$0.00
1	FRONT RH HEAD LAMP ASSY	MTG BROKEN	\$3,808.90	\$3,808.90
1	RH HEAD GARNISH	NOT NECESSARY	\$248.20	\$0.00
1	FRONT GRILLE ASSY	NOT NECESSARY	\$2,038.00	\$0.00
	LESS 0.00 / 25.00% DISCOUNT		\$0.00	(\$1,283.73)
			\$10,512.40	\$3,851.17

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
10	FRONT BUMPER CLIPS @\$7.00 (SN)	NECESSARY	\$70.00	\$20.00
			\$70.00	\$20.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING & REMOVE & REFIT HEADLAMP		\$180.00	\$30.00
	TO KNOCKING STRAIGHTENING REPAIR & RENEW ALL ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF FRONT RH FENDER.		\$1,000.00	\$400.00
	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA (PEARL WHITE)		\$1,200.00	\$500.00
			\$2,380.00	\$930.00

GRAND TOTAL			\$12,962.40	\$4,801.17
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,800.00

Report Ref No: CD/FCI24090057/Dma3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ABT

ANG BRYAN TANI


DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SKQ 69H



PHOTOGRAPHS FOR VEHICLE NO. : SKQ 69H



PHOTOGRAPHS FOR VEHICLE NO. : SKQ 69H





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 8)

PHOTOGRAPHS FOR VEHICLE NO. : SKQ 69H



PHOTOGRAPHS FOR VEHICLE NO. : SKQ 69H



PHOTOGRAPHS FOR VEHICLE NO. : SKQ 69H



PHOTOGRAPHS FOR VEHICLE NO. : SKQ 69H



PHOTOGRAPHS FOR VEHICLE NO. : SKQ 69H



PHOTOGRAPHS FOR VEHICLE NO. : SKQ 69H



PHOTOGRAPHS FOR VEHICLE NO. : SKQ 69H



PHOTOGRAPHS FOR VEHICLE NO. : SKQ 69H



PHOTOGRAPHS FOR VEHICLE NO. : SKQ 69H



PHOTOGRAPHS FOR VEHICLE NO. : SKQ 69H





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SKQ 69H

