

ASS. REC. BY:

REF:

LPC / 24090062/kmaz

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMK 9885J

Yr Regn: 031 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Premio F

C.C. 1496

Colour

M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

456409

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NET 260 3035008

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / A/Rlm or

Tyre Size:

F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

Rear

R/Bal.

9 mm

R/Bal. 9 mm

L/Bal.

9 mm

L/Bal. 9 mm

D.O.A.

31/8/24

D.O.I. 4/9/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/9 11:00 @ 4550h Car

Date/Time, File Pass to?



: Prell. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SMK98855

NOT Withheld
L1 Day @ 4550h
Repair After Rain
5 days

No.	Qty	List Items	
1	1	Rear bumper	\$ Bu 753.10 —
2	2	Rear bumper side retainer	\$ In 313.40 X
3	2	Rear bumper inner side impact bracket	\$ Di 1 Di 266.40 —
4	1 set	Rear bumper clips	\$ In 50.00 —
5	2	Taillamp	\$ 955.60 — 477.80
6	1	Rear boot lid	\$ Bu 1 In 1,277.60 —
7	1	Rear boot centre top "TOYOTA" logo	\$ In 67.80 —
8	1	Rear boot RH "F" emblem	\$ In 54.30 —
9	1	Rear boot LH "PREMIO" emblem	\$ In 81.70 —
10	2	Rear boot side lamp	\$ 757.80 —
11	1	Rear boot outer chrome handle	\$ In 331.60 —
12	1	Rear boot top lock	\$ In 323.75 X
13	1	Rear boot weatherstrip	\$ 12585 Di 1 In 251.70 50 In
14	1	Rear end panel	\$ In 931.75 —
15	1	Rear end panel top garnish	\$ In 189.70 —
			\$ 6,606.20
		Less 25%	\$ 1,651.55
		Total :	\$ 4,954.65

Special Nett Items

16	1 set	Rear end panel sealant	\$ In 60.00 30 In
17	1 set	Rear bumper reverse sensor	\$ In 280.00 20 In
18	1	Rear number plate	\$ In 50.00 X
		Total :	\$ 390.00

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$ 900.00 600
2	To putty and spray Spray Paintings charges.	\$ 1,000.00 600
3	To check wirings and lightings.	\$ 40.00 20
4	To remove, refit reverse sensors.	\$ 80.00 50
5	To remove, refit rear upholstery & attachemnts.	\$ 120.00 60
6	To remove, refit rear boot fittings.	\$ 80.00 50
7	To supply and apply anti rust treatment	\$ 80.00 60
	Total :	\$ 2,300.00

Total Parts and Labour : \$ 7,644.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: