



ESTABLISHED 1984

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: JULIE

Ref: CS/INC24090063/Avh3m4(N)

Date: 06/02/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 2231H	Veh. Inspected	SCG 2840G
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1293425-001	Excess (\$)	0.00
Assign From	JESS TOH	Assign Date	04/09/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VELLFIRE	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ANH208347158	Colour	WHITE
Odometer	213406 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50R18	CONTINENTAL	6 mm
L/H Front Tyre	235/50R18	CONTINENTAL	6 mm
R/H Rear Tyre	235/50R18	CONTINENTAL	6 mm
L/H Rear Tyre	235/50R18	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/08/2024	Inspect Date / Time	04/09/2024 (11:50 AM)
Survey held at	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**