

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate: \_\_\_\_\_

OD / TP RES / CD RES / EVA / INV / MV

To in \_\_\_\_\_ Vehicle No: \_\_\_\_\_

at \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Vehicle: \_\_\_\_\_

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repair: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: G B6443SS Yr Regn: 2017, August.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna C.V. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 158231 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTFAT35Y 70K208531

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 155 R13C

R: 155 R12

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. \_\_\_\_\_

Survey held at

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. 10/09/24

A-Tec

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Liberty.

COE Expiry

Estimate given during : Yes ✓

1st Survey : No C

MV: 42K

PV: 11.3K

Nett: 30.7K

381D.

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Inve (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

Report Formist:

Report Formist:

A-Tec Automotive Pte Ltd  
8 Kaki Bukit Ave 4  
#04-20 Premier  
Singapore 415875

10 Sep 2024

**GBG 4435 S TOYOTA DYNA**

| No | Qty | Parts Description                      | Estimated Parts Price           |
|----|-----|----------------------------------------|---------------------------------|
| 1  | 1   | Rear tailboard lower panel <i>pipe</i> | \$ 878.50 <i>X</i>              |
| 2  | 2   | Rear taillamps <i>RH int</i>           | \$ <del>659.30</del> <i>245</i> |
| 3  | 2   | Rear taillamp panels <i>new</i>        | \$ 399.00 <i>X</i>              |
| 4  | 1   | Rear number plate panel <i>best</i>    | \$ 98.50 <i>✓</i>               |
| 5  | 2   | Rear number plate lamps <i>new</i>     | \$ 179.30 <i>X</i>              |
| 6  | 1   | Rear exhaust pipe <i>new</i>           | \$ 752.60 <i>X</i>              |
| 7  | 1   | Rear exhaust mounting <i>new</i>       | \$ 48.90 <i>X</i>               |
|    |     |                                        | \$ 3,016.10                     |
|    |     |                                        | less 25%                        |
|    |     |                                        | \$ 754.03                       |
|    |     |                                        | <u>\$ 2,262.08</u>              |

| No                        | Qty | Parts Description                           | Estimated Parts Price              |
|---------------------------|-----|---------------------------------------------|------------------------------------|
| <u>Special Nett Items</u> |     |                                             |                                    |
| 1                         | 1   | Rear tailboard "12 PAX" sticker <i>new</i>  | \$ <del>25.00</del> <i>15</i>      |
| 2                         | 1   | Rear tailboard "70KM/H" sticker <i>new</i>  | \$ 25.00 <i>X</i>                  |
| 3                         | 1   | Rear number plate <i>Best</i>               | \$ <del>50.00</del> <i>30</i>      |
| 4                         | 1   | Rear reverse sensor (1 set) <i>new</i>      | \$ 280.00 <i>X</i>                 |
| 5                         | 1   | Rear tailboard -LH <i>new</i>               | \$ 1,800.00 <i>X</i>               |
| 6                         | 1   | Rear tailboard -RH <i>Dented</i>            | \$ <del>1,800.00</del> <i>1200</i> |
| 7                         | 2   | Rear tailboard lock bars <i>Broken</i>      | \$ <del>960.00</del> <i>800</i>    |
| 8                         | 2   | Rear tailboard lock bar strikers <i>new</i> | \$ 230.00 <i>X</i>                 |
| 9                         | 2   | Rear tailboard lower hinges <i>new</i>      | \$ 290.00 <i>X</i>                 |
|                           |     |                                             | <u>\$ 5,460.00</u>                 |

**Total parts : \$ 7,722.08**

| No                    | Description                                                                                                                                                              | Labour Charges              |
|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|
| 1                     | To remove, refit, replaced damaged lamps and check up rear electrical wiring                                                                                             | \$ 80.00 <del>30</del>      |
| 2                     | To remove and refit rear reverse sensor.                                                                                                                                 | \$ 150.00 <del>150</del>    |
| 3                     | To apply undercoating on repaired and replaced panel.                                                                                                                    | \$ 150.00 <del>X.</del>     |
| 4                     | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident. | \$ 1,800.00 <del>400.</del> |
| 5                     | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.                                          | \$ 1,600.00 <del>400.</del> |
| <b>Total labour :</b> |                                                                                                                                                                          | <u>\$ 3,780.00</u>          |

|                            |                     |
|----------------------------|---------------------|
| <b>Total parts :</b>       | \$ 7,722.08         |
| <b>Total labour :</b>      | \$ 3,780.00         |
| <b>Total repair cost :</b> | <u>\$ 11,502.08</u> |

Adrian Lj  
 L/S 10/09/24.  
 OH Days.