

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24060143/KMA3Q2**Date:** 05/08/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7220068037-02  
**Claimant Vehicle No :** SNR49A **Insured Vehicle No :** SNG555M  
 Date of Loss: 15/06/2024 Nature of Claim: TP Claim No: 8454787305SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNR49A**  
 Make & Model: TESLA MODEL 3 PERFORMANCE, (A) Engine No: HIDDEN  
 Reg. Date: 03/09/2021 (Man. Year: 2021) Chassis No: LRW3F7ELXMC283029  
 Colour: Metallic Pearl White Odometer: 53504 km  
 Engine Capacity: 0 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35Z R20 Rear Tyre Size: 285/30Z R20  
 Front Left Side: Continental 7 mm Rear Left Side: Continental 7 mm  
 Front Right Side: Continental 7 mm Rear Right Side: Continental 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	80.00	0.00	80.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	450.00	280.00	170.00	37.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>530.00</b>	<b>280.00</b>	<b>250.00</b>	<b>47.17</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment: 19/06/2024  
 Date Inspected: 19/06/2024 Inspected At: Optima Werkz Pte Ltd (HQ)  
 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK  
 Autopoint  
 Singapore 568047  
 Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG**Manager:** Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHR DOOR (NPA)	Repair	0.00 FL	*- FL
2	1		*NANO COATING	*Check	80.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					80.00	0.00
- List Item Discount on L Items 10.00/10.00% (\$)					0.00	0.00
Total Parts (\$)					80.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REPLACE ,REPAIR READJUST & REFIX SIDE AFFECTED AREAS	New	200.00	60.00
2	TO REMOVE ,PUTTY ,REPAIR SAND AND RESPRAY AFFECTED AREAS	New	250.00	220.00
<b>Gross Labour Cost (\$\$)</b>			<b>450.00</b>	<b>280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >