



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRE SINGAPORE 189557		Ref: Date: Code:	CS/INC24060144/Unh3m4 16/07/2024 INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SDE 8204C	Veh. Inspected	SJP 5231P
	Policy No.	-	Coverage	0
	Claim No.	MT/1281562-002	Excess	\$0.00
	Assign From	SITI RAUDHAH	Assign Date	19/06/2024
2. Vehicle Details				
	Make & Model	TOYOTA HARRIER G GRADE (A)		C.C
	Engine No.	8ARZ095480		Year of Reg.
	Chassis No.	JTEKB3GHX0J000531		Colour
	Odometer	91361 KM		Steering
	Brakes	IN ORDER		General
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	235/55R18	YOKOHAMA	6
	L/H Front Tyre	235/55R18	YOKOHAMA	6
	R/H Rear Tyre	235/55R18	YOKOHAMA	6
	L/H Rear Tyre	235/55R18	YOKOHAMA	6
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	12/06/2024		Inspection Date
	Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				