



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 3064C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT FENDER	CRACKED	110.00	110.00
1	FRONT FORK ASSY	BENT	750.00	550.00
1	FRONT FORK UNDER BRACKET	NECESSARY	250.00	200.00
1	FRONT COWLING	CRACKED	145.00	145.00
1	FRONT COWLING LOWER GARNISH	CRACKED	78.00	78.00
1	FRONT COWLING INNER SHIELD	CRACKED	215.00	215.00
1	FRONT SIDE COWLING	CUT	150.00	150.00
1	FRONT SIGNAL LAMP	CRACKED	188.00	188.00
1	BALANCER	CUT	50.00	50.00
1	FRONT WING MIRROR	DAMAGED	128.00	128.00
1	HANDLE SHIELD	CUT	105.00	105.00
1	FRONT FOOTREST RUBBER	CUT	45.00	45.00
1	FRONT FOOTREST BRACKET	BENT	140.00	140.00
1	SIDE MAIN	BENT	115.00	115.00
1	MAIN STAND	NOT NECESSARY	148.00	-
1	FOOT LEVER	BENT	80.00	80.00
1	REAR FOOTREST RUBBER	CUT	45.00	45.00
1	REAR FOOTREST BRACKET	CRACKED	95.00	95.00
1	SWING ARM	NOT NECESSARY	558.00	-
	LESS 10% DISCOUNT		-339.50	-243.90
			3,055.50	2,195.10
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FORK OIL (SN)	NECESSARY	40.00	40.00
1	FORK OIL SEAL (SN)	NECESSARY	30.00	30.00
1	STEERING CONE & BEARING (SN)	NECESSARY	120.00	120.00
1	HANDPHONE HOLDER (SN)	DAMAGED	100.00	50.00
1	REAR THERMAL STORAGE BAG (SN)	NOT NECESSARY	280.00	-
1	REAR THERMAL STORAGE BAG BRACKET (SN)	NOT NECESSARY	250.00	-
			820.00	240.00

Report Ref No. CS/INC24090083/Aqh3m4(N)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	PANEL BEATING, REMOVE AND REFIT PARTS.		400.00	200.00
	SPRAY PAINTING TO AFFECTED AREA.		400.00	200.00
	WIRING CHECK.		50.00	30.00
	TO STRAIGHTEN BODY CHASSIS.	NOT NECESSARY	300.00	-
			1,150.00	430.00
	<b>GRAND TOTAL</b>		<b>5,025.50</b>	<b>2,865.10</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>2,200.00</b>

Report Ref No. CS/INC24090083/Aqh3m4(N)

TOTAL FOR SPARE PARTS: \$ 3,875.50 \$ 2,435.10

TOTAL FOR LABOUR : \$ 1,150.00 \$ 430.00

TOTAL REPAIR COST: \$ 5,025.50 \$ 2,865.10

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.