

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24090088/RNP3E2
Date: 13/09/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	YP6863G	Insured Vehicle No :	GBL1609B
Date of Loss:	31/08/2024	Nature of Claim:	TP
		Claim No:	DMCV2400175H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP6863G	Engine No:	4P10C76748
Make & Model:	MITSUBISHI FEB21ER3SDEN, 3.0 D (A)	Chassis No:	FEB21EA21423
Reg. Date:	28/07/2017 (Man. Year: 2017)	Odometer:	312242 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C (D)
Front Left Side:	Austone 7 mm	Rear Left Side:	Austone 7/7 mm
Front Right Side:	Austone 7 mm	Rear Right Side:	Austone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,538.77	6,536.28	1,002.49	13.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,800.00	1,400.00	43.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,738.77	8,336.28	2,402.49	22.37
Approved Total (Overridden) (S\$)		6,650.00		
(S\$)	10,738.77	6,650.00	4,088.77	38.07
+ GST 9.00/9.00% (S\$)	966.49	598.50	367.99	38.07
Nett Amount (S\$)	11,705.26	7,248.50	4,456.76	38.07

INSPECTION

Date of Assignment:	05/09/2024	
Date Inspected:	05/09/2024	Inspected At: Venda Engineering & Trading Pte Ltd (HQ) Level 5, 8 Tuas Avenue 18 Singapore 638892
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 13 Sep 2024)	
Parts:	N/A	MITSUBISHI FEB21ER3SDEN 3.0 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP6863G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT MIRROR STAY, LH	Cracked	462.56 FL	*462.56 FL
2	1	*FRONT SIDE MIRROR, LH	Cracked	124.50 FL	*124.50 FL
3	1	*FRONT ROUND MIRROR, LH	Cracked	98.20 FL	*98.20 FL
4	1	*FRONT MIRROR STAY COVER, LH	Missing	95.20 FL	*95.20 FL
5	1	*FRONT CORNER PANEL TOP GARNISH, LH	Missing	94.94 FL	*94.94 FL
6	1	*FRONT CORNER PANEL, LH	Not Necessary	521.59 FL	*- FL
7	3	*FRONT CORNER PANEL CLIP, LH	Not Necessary	30.00 FL	*- FL
8	1	*FRONT SIGNAL LAMP, LH	Cracked	280.59 FL	*280.59 FL
9	1	*FRONT HEADLAMP, LH	Not Necessary	492.21 FL	*- FL
10	1	*FRONT HEADLAMP SIDE COVER, LH	Not Necessary	226.19 FL	*- FL
11	1	*FRONT DOOR, LH	Bent	1,983.46 FL	*1,983.46 FL
12	1	*FRONT PILLAR B, LH	Cracked	1,815.59 FL	*1,815.59 FL
13	1	*COMPANY LOGO STICKER	Necessary	150.00 FS	*100.00 FS
14	1	*FRONT FREEZER BOX BOTTOM ALUMINIUM CORNER CAP	Cracked	200.00 FS	*200.00 FS
15	1	*FRONT FREEZER BOX ALUMINIUM BOTTOM CORNER FRAME, LH	Cracked	200.00 FS	*200.00 FS
16	1	*FRONT FREEZER BOX GRP BOARD, LH	Cracked	300.00 FS	*300.00 FS
17	1	*FREEZER BOX DOOR LONG GASKET, LH	Scratched	300.00 FS	*300.00 FS
18	1	*FREEZER BOX DOOR SHORT GASKET, LH	Cracked	220.00 FS	*220.00 FS
19	1	*FREEZER BOX DOOR BOTTOM S/STEEL FRAME, LH	Bent	1,000.00 FS	*1,000.00 FS
20	1	*FRONT FREEZER BOX ALUMINIUM CORNER FRAME, LH	Cracked	500.00 FS	*500.00 FS
				Sub Total (\$\$)	9,095.03 7,775.04
				- List Item Discount on L Items 25.00/25.00% (\$\$)	1,556.26 1,238.76
				Total Parts (\$\$)	7,538.77 6,536.28

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & RENEW PARTS, PANEL BEAT & RE-ALIGN LH PORTION	New	1,000.00	500.00
2	REMOVE & RENEW PARTS, CUT & WELD FREEZER BOX LH DOOR BOTTOM S/STEEL FRAME	New	1,000.00	500.00
3	TO SUPPLY & CONNECT NEW WIRING	New	200.00	100.00
4	PUTTY & SPRAY PAINT FRONT LH CORNER PANEL, FRONT LH DOOR, FRONT LH PILLAR B & REAR LH FREEZER BOX PORTION	New	1,000.00	700.00
Gross Labour Cost (S\$)			3,200.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >